



I N F I N I T I

TECHNICAL SERVICE BULLETIN

| | | |
|------------------------------|--------------------------|----------------------------|
| Classification: AN23-006E | Reference: ITB23-010E | Date: February 22, 2024 |
|------------------------------|--------------------------|----------------------------|

SOFTWARE UPDATE FOR INFOTAINMENT ISSUES

| | |
|--------------------------|-----------------------|
| APPLIED VEHICLES: | 2016-2023 Q50 (V37) |
| | 2017-2022 Q60 (CV37) |
| | 2018-2019 Q70 (Y51) |
| | 2017-2019 QX30 (H15) |
| | 2019-2023 QX50 (J55) |
| | 2022-2023 QX55 (FJ55) |
| | 2015-2020 QX60 (L50) |
| | 2022-2023 QX60 (L51) |
| | 2015-2023 QX80 (Z62) |

This bulletin is no longer active.

To access infotainment software updates via the Infotainment Software Update Utility:

Select **SPECIALTY TOOLS**, and then select **Infotainment Software Updates** on the left side of ASIST.

Please discard previous versions of ITB23-010.

AMENDMENT HISTORY

| PUBLISHED DATE | REFERENCE | DESCRIPTION |
|-------------------|------------|--|
| March 8, 2023 | ITB23-010 | Original bulletin published |
| April 4, 2023 | ITB23-010A | Vehicle tables on pages 5, 6, 9, 10, 13, and 14 updated, Install 1 procedure revised. CLAIMS INFORMATION updated |
| August 1, 2023 | ITB23-010B | Vehicle tables on pages 12 and 14 updated |
| August 16, 2023 | ITB23-010C | NOTICE statement added to page 3 |
| January 24, 2024 | ITB23-010D | Bulletin no longer active |
| February 22, 2024 | ITB23-010E | Revised to remove HINT about Utility availability |