

WPR3 Workshop Campaign - Replacing gearshift paddles

WPR3 Workshop Campaign - Replacing gearshift paddles

ID Number	WPR3
Models	911 GT3 RS (992)
Model Years	2023 - 2024
VIN List	Attached
Number of Affected VINs	265
Issue Description	<p>Due to a temporary manufacturing error, shift paddles which do not meet the required specifications were installed on the steering wheels in affected vehicles.</p> <p>For this reason, the steering wheel shift paddles in the affected vehicles must be replaced.</p>
What should Porsche Centers do?	<p>Please arrange for this measure to be carried out as soon as possible on affected vehicles.</p> <p>As of the time of this posting (4/10/24) the remedy is now available.</p> <p>Parts can be ordered via PPL as normal.</p>
TI Number	No. 183-23
Customer Notification	To be posted at a later date.

Required parts

Part number	Designation	Quantity/vehicle	Parts return*
V04015004LM5Q0	Black shift paddle (set)	1 piece	No
N 90799102	M18 x 1.5 x 18 counter-sunk screw with internal serration	1 piece	No

*The parts must be stored until such time as the related warranty or campaign claim has been credited. If a barcode is generated with the credit note, the affected part must be sent to Porsche AG as usual. If no barcode is generated with the credit note, the part can go directly into the remanufactured parts process or be scrapped.

Warranty processing

Validity:

This workshop campaign will be carried out up to March 6th, 2029 and will be closed on that date.

Please note that warranty claims can only be processed up to this date.

Scope 1:

Damage Code	WPR3 66 000
Repair Code	2
Labor time	61 TU

Please enter the campaign carried out in the Warranty and Maintenance booklet for the vehicle.

Customer mobility

If requested, mobility for the affected customer can be ensured by offering a suitable replacement transport.

Please invoice this additional service via WWS with the campaign scope.

Attachments

1. [VIN_List_Report_WPR3_2024-04-10_V2.xlsx](#)