

**SB-10052838-1969**

**ONLINE AUTOMOTIVE SERVICE INFORMATION SYSTEM  
FOR AUGUST 2013**

44139

2011-2013 Fiesta May Exhibit A Hood Cable Buzz Noise That May Sound Like An Exhaust Noise.

Some 2011-2014 Fiesta vehicles may exhibit a hood cable buzz noise that may sound like an exhaust noise. Typical complaint is sound from drivers side exterior bulkhead during light/medium acceleration after coasting in 3rd gear (approximately 1800-2200 RPM). It may be duplicated by revving engine at idle to 2500 RPM. Using chassis ears, the sound appears to come from throttle body. The inner hood cable may be vibrating within the cable casing. Before replacing parts apply slight tension to the interior hood release handle while noise is present. Be careful not to open hood. If noise changes with cable tension, inspect cable routing. The buzz seems to occur more when cable routed in front of air cleaner assembly.