

**ONLINE AUTOMOTIVE SERVICE INFORMATION SYSTEM
FOR MAY 2013**

32241 2011 - 2013 Multiple Vehicle Lines With MyTouch - Touchscreen Calibration Process

For vehicle lines equipped with MyTouch, touchscreen calibration must be performed after any APIM programming, replacement or disconnect from Front Display Interface Module (FDIM). The touchscreen calibration is accomplished through either scan tool directions or WSM section 415-00, General Procedures for APIM programming and using the second to last step or from General Procedures, Touchscreen Calibration. Workshop Manuals are being updated to reflect calibration needs for FDIM during removal/replacement.