

**ONLINE AUTOMOTIVE SERVICE INFORMATION SYSTEM  
FOR JUNE 2013**

32251 2012-2013 Multi Vehicle Line - Intermittent/Inoperative Integrated Keyhead Transmitter (IKT)

Some 2012-2013 F150/Superduty/Expedition/Navigator/Flex/Edge/Explorer/ Taurus/Mustang vehicles built between 9/1/2011 and 12/1/2012 without Intelligent Access or push button start may have an intermittent/inoperative IKT with symptoms similar to a discharged IKT battery. This concern is under investigation and repairs should not be performed at this time, please continue to monitor oasis for updates.