

**ONLINE AUTOMOTIVE SERVICE INFORMATION SYSTEM  
FOR JUNE 2013**

32270 2008-2013 F150, Expedition, Navigator and 2008 Mark LT 4x4 Intermittent Noise From Front In 4x2 Mode Only - WSM Update

Some 2008 - 2013 F150, Expedition, Navigator and 2008 Mark LT vehicles equipped with 4x4 may exhibit a noise from the front hub Integrated Wheel End (IWE) areas while operating in 4x2 mode. The noise will cease when the shifted into 4x4 mode. The WSM section 308-07A has been updated to address possible concerns that can occur during IWE installation to include CV shaft to inner bearing depth specification. Installing the axle nut and tightening without proper depth of protrusion will result in damage to the IWE.