

**ONLINE AUTOMOTIVE SERVICE INFORMATION SYSTEM
FOR SEPTEMBER 2013**

44183 2013-2014 F-Super Duty - 6.7L Diesel - MIL On With DTC P246F, P246E, P242A, P22FF, P2080, P2084, P242B, P2470, P2031, P0544 - EGT Sensor Replacement

Some 2013 F-Super Duty vehicles equipped with a 6.7L Diesel engine may exhibit DTCs P246F, P246E, P242A, P22FF, P2080, P2084, P242B, P2470, P2031, P0544. When diagnosing any of these DTCs, if normal PC/ED diagnostics lead to replacement of an EGT sensor, replace the sensor and the corresponding connector on the wire harness using pigtail kit (3U2Z-14S411-BXAB).