

ONLINE AUTOMOTIVE SERVICE INFORMATION SYSTEM
FOR JANUARY 2014

SB-10055041-2768

44383 2009-2014 F150 4x4 Front Pinion Bearing Damage

If pinion bearing damage is noted during the repair of the Front Axle on 2009 - 2014 F150 4x4 units operated in severe cold climates. Use Motorcraft XY-75W85-QL Synthetic Hypoid Gear Lubricant upon reassembly and fluid fill. The lube will offer better pinion bearing lubrication in severe arctic conditions. Only a small number of units operated in the most severe climates will benefit from the using the synthetic lube. Do not replace the lube unless you have identified a concern with the pinion bearing.