

**ONLINE AUTOMOTIVE SERVICE INFORMATION SYSTEM
FOR MAY 2014**

SB-10056191-9916

44538 4R75E Transmission - Slipping 3rd and 4th Gears - No 4th Gear DTC P0733 P0734

Some 2008 Mark LT, 2008-2010 F-150, 2008-2011 Crown Victoria, Grand Marquis, Town Car, and 2008-2013 E-Series vehicles equipped with a 4R75E transmission may exhibit an illuminated Overdrive Off indicator, and/or slipping in 3rd gear and/or no 4th gear, and/or DTCs P0733 and/or P0734. These conditions may be due to a direct clutch failure. The parts required to repair this condition are now available in a new direct clutch kit, which includes a direct clutch hub. Order kit part number 9L3Z-7F283-A. Refer to published Service Labor Time Standards.