45290

2015 Edge - Reverse Lamp Assembly Replacement - Rear View Camera - Inoperative Gridlines And/Or DTC B115E - Rear View Camera Configuration

Some 2015 Edge vehicles equipped with rear view camera may require the rear view camera configuration to be completed when replacing the reverse lamp assembly. Active grid lines may not show and/or DTC B115E:55 may be present if not configured. If the new reverse lamp assembly comes equipped with a new camera, the new camera will need to be configured using the IDS tool. To configure the new camera, go to the Toolbox tab, Electrical, Service Functions, and LIN New Module Initialization. If the new reverse lamp assembly is not equipped with a new camera, then the original camera should be swapped from the old reverse lamp assembly to the new reverse lamp assembly. When transferring the original camera from the old reverse lamp assembly to the new reverse lamp assembly, the rear view camera configuration does not need to be performed.