	I Tech Tip	S-TT-0074-13	Market	October 28, 201
R-S FIPG Rec	ommendation for	r Engine repairs	The state of the	
ervice Category Engine/Hybrid Syster	m	Section Engine Mec	nanical	
oplicability 013-2014 Scion FR				
APPLICABLE VEHICLE	s		1. March 1.	
2013-2014		FR-S		
	air manual calls for the u	se Three Bond 12170	G or equivalent (TI	B 1217H) when
	al Engine repairs on the			
0103) is NOT comp 217H directly from 1	atible with TB 1217G or i	its equivalent. See rec	commendation bel	ow to purchase
	Theebond.			
and the second				
RECOMMENDATIONS		And the second states in the	and the second second second	
	urebase 1017H seclarity	from Three Dond Doo		broo Dond using
oyota dealers can p	purchase 1217H sealant t	from ThreeBond. Dea	lers can contact T	hreeBond using
		from ThreeBond. Dea	lers can contact T	hreeBond using
oyota dealers can p one of the methods b • e-mail:	oelow: sales@threebond.com			hreeBond using
oyota dealers can p one of the methods b e-mail: Direct (below: sales@threebond.com Customer Service: 513-7			hreeBond using
oyota dealers can p one of the methods b e-mail: Direct (oelow: sales@threebond.com			hreeBond using
oyota dealers can p one of the methods b e-mail: Direct 0 Sales F	below: sales@threebond.com Customer Service: 513-7	59-8762 Carla Sallee-	Rosselot	
oyota dealers can p one of the methods b e-mail: Direct (Sales F Dealers should note Dealers will need to p	below: sales@threebond.com Customer Service: 513-7 Fax: 513-779-7375 that the sealant is availal provide dealer code, dea	59-8762 Carla Sallee- ble in multiples of 6 tu	Rosselot bes (each tube, 1	50 g or 5 oz).
oyota dealers can p one of the methods b e-mail: Direct 0 Sales F Dealers should note	below: sales@threebond.com Customer Service: 513-7 Fax: 513-779-7375 that the sealant is availal provide dealer code, dea	59-8762 Carla Sallee- ble in multiples of 6 tu	Rosselot bes (each tube, 1	50 g or 5 oz).
oyota dealers can p one of the methods b e-mail: Direct (Sales F Dealers should note Dealers will need to p	below: sales@threebond.com Customer Service: 513-7 Fax: 513-779-7375 that the sealant is availal provide dealer code, dea	59-8762 Carla Sallee- ble in multiples of 6 tu	Rosselot bes (each tube, 1	50 g or 5 oz).
oyota dealers can p one of the methods b e-mail: Direct 0 Sales F Dealers should note Dealers will need to p or purchase/paymer	below: sales@threebond.com Customer Service: 513-7 Fax: 513-779-7375 that the sealant is availal provide dealer code, dea	59-8762 Carla Sallee- ble in multiples of 6 tu lership name, etc. De	Rosselot bes (each tube, 1 alers must have c	50 g or 5 oz).
oyota dealers can p one of the methods b e-mail: Direct 0 Sales F Dealers should note Dealers will need to p or purchase/paymer	below: sales@threebond.com Customer Service: 513-7 Fax: 513-779-7375 that the sealant is availal provide dealer code, dea ht. Sealants required for Sci	59-8762 Carla Sallee- ble in multiples of 6 tu lership name, etc. De ion FR-S Engine Meck DESCRIPTION	Rosselot bes (each tube, 1 alers must have c nanical Repairs	50 g or 5 oz). redit card ready
oyota dealers can p one of the methods b e-mail: Direct (Sales F Dealers should note Dealers will need to p or purchase/paymer	sales@threebond.com Customer Service: 513-7 Fax: 513-779-7375 that the sealant is availal provide dealer code, dea nt. Sealants required for Sci CURRENT TOYOTA # N/A	59-8762 Carla Sallee- ble in multiples of 6 tu lership name, etc. De ion FR-S Engine Mech DESCRIPTION FIPG ENGINE (GRAY)	Rosselot bes (each tube, 1 alers must have c nanical Repairs THREEBOND @ TB 1217G	50 g or 5 oz). redit card ready
oyota dealers can p one of the methods b e-mail: Direct (Sales F Dealers should note Dealers will need to p or purchase/paymer	sales@threebond.com Customer Service: 513-7 Fax: 513-779-7375 that the sealant is availal provide dealer code, dea nt. Sealants required for Sci	59-8762 Carla Sallee- ble in multiples of 6 tu lership name, etc. De ion FR-S Engine Meck DESCRIPTION	Rosselot bes (each tube, 1 alers must have c nanical Repairs	50 g or 5 oz). redit card ready
oyota dealers can p one of the methods b e-mail: Direct (Sales F Dealers should note Dealers will need to p or purchase/paymer	sales@threebond.com Customer Service: 513-7 Fax: 513-779-7375 that the sealant is availal provide dealer code, dea nt. Sealants required for Sci CURRENT TOYOTA # N/A	59-8762 Carla Sallee- ble in multiples of 6 tu lership name, etc. De ion FR-S Engine Mech DESCRIPTION FIPG ENGINE (GRAY)	Rosselot bes (each tube, 1 alers must have c nanical Repairs THREEBOND @ TB 1217G	50 g or 5 oz). redit card ready
oyota dealers can p one of the methods b e-mail: Direct (Sales F Dealers should note Dealers will need to p or purchase/paymer PREVIOUS TOYOTA # N/A	sales@threebond.com Customer Service: 513-7 Fax: 513-779-7375 that the sealant is availal provide dealer code, dea nt. Sealants required for Sci CURRENT TOYOTA # N/A	59-8762 Carla Sallee- ble in multiples of 6 tu lership name, etc. De ion FR-S Engine Mech DESCRIPTION FIPG ENGINE (GRAY)	Rosselot bes (each tube, 1 alers must have c nanical Repairs THREEBOND @ TB 1217G	50 g or 5 oz). redit card ready
oyota dealers can p one of the methods b e-mail: Direct (Sales F Dealers should note Dealers will need to p or purchase/paymer	sales@threebond.com Customer Service: 513-7 Fax: 513-779-7375 that the sealant is availal provide dealer code, dea nt. Sealants required for Sci CURRENT TOYOTA # N/A	59-8762 Carla Sallee- ble in multiples of 6 tu lership name, etc. De ion FR-S Engine Mech DESCRIPTION FIPG ENGINE (GRAY)	Rosselot bes (each tube, 1 alers must have c nanical Repairs THREEBOND @ TB 1217G	50 g or 5 oz). redit card ready
Toyota dealers can point of the methods being of the methods of the met	sales@threebond.com Customer Service: 513-7 Fax: 513-779-7375 that the sealant is availal provide dealer code, dea nt. Sealants required for Sci CURRENT TOYOTA # N/A	59-8762 Carla Sallee- ble in multiples of 6 tu lership name, etc. De ion FR-S Engine Mech DESCRIPTION FIPG ENGINE (GRAY)	Rosselot bes (each tube, 1 alers must have c nanical Repairs THREEBOND @ TB 1217G	50 g or 5 oz). redit card ready

Ver. 2.1 8/28/2011 S

© 2013, Toyota Motor Sales, USA