

Technical Service Bulletin Number
--

TSB150014



Technical Service Bulletin

Subject

Premium Exhaust Manifold Gasket for C Gas Plus

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This document introduces a premium exhaust manifold gasket.

Product Affected

C Gas

C Gas Plus

Description of Change

The premium gasket has a five layer design while the standard has only one layer.

Service Instructions

Use of the premium exhaust manifold gasket is recommended when replacement is required.

Service Parts Availability

Service parts are available. See Table 1 for part numbers.

Table1, Exhaust Manifold Gasket Part Numbers		
Part Description	Standard Part Number	Premium Part Number
Exhaust Manifold Gasket	3929012	3932063

Part Structure

The premium part number does **not** obsolete and supersede the standard part number.

The standard part number will remain available.

Document History

Date	Details
2015-2-11	Module Created

Last Modified: 13-Feb-2015

Copyright © 2000-2010 Cummins Inc. All rights reserved.