

SSM
46358

2011-2017 Fiesta and 2012-2017 Focus Service Pigtail for Transmission Control Module connector C1750A is available. If repairs are needed use part number FU2Z-14S411-VA. Replacement of wiring harness 12A581 is no longer required when this connector needs servicing.