



© 2014 Mazda Motor of America, Inc.

| | |
|--|--------------------------------|
| Subject: MAZDA SERVICE PROGRAM (MSP36) - NONCONFORMITY TO EVAPORATIVE EMISSION STANDARD | Bulletin No: 01-003/14 |
| | Last Issued: 02/11/2014 |

BULLETIN NOTE

MAZDA SERVICE PROGRAM (MSP36) RELEASED AS BULLETIN 01-020/12 ON 06/18/12 IS NO LONGER VALID. IT HAS BEEN SUPERCEDED BY "2007-2012 CX-7 NONCONFORMITY TO EVAPORATIVE EMISSION STANDARD - EMISSION RECALL 7113L".

APPLICABLE MODEL(S)/VINS

2007-2012 CX-7 equipped with L3T (turbo) engine and produced from February 14, 2006 through April 26, 2012

- 2007 VIN Range: JM3 ER**** 70 100057 – 169185
- 2008 VIN Range: JM3 ER**** 80 169188 – 215755
- 2009 VIN Range: JM3 ER**** 90 215758 – 238633
- 2010 VIN Range: JM3 ER**** A0 300038 – 353038
- 2011 VIN Range: JM3 ER**** B0 353048 – 410354
- 2012 VIN Range: JM3 ER**** C0 410407 – 424994

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.