



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

August 9, 2022

Mr. Gregory Vismara
Vice President Engineering
Gillig, LLC
25800 Clawiter Road
Hayward, CA 94545

NEF-107MR
22V-548

Subject: Battery Pack May Short and Cause Fire

Dear Mr. Vismara:

This letter serves to acknowledge Gillig, LLC's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

GILLIG/LOW FLOOR/2019-2022

Mfr's Report Date: July 28, 2022

NHTSA Campaign Number: 22V-548

Components:

ELECTRICAL SYSTEM:PROPULSION SYSTEM:TRACTION BATTERY

Potential Number of Units Affected: 184

Problem Description:

Gillig, LLC (Gillig) is recalling certain 2019-2022 Low Floor vehicles equipped with Cummins BP74E battery packs. The battery packs may develop a coolant leak internally, causing the battery pack to short circuit.

Consequence:

A battery short circuit increases the risk of a fire.

Remedy:

Gillig will tighten the coolant fittings and replace the coolant, free of charge. Owner notification letters are expected to be mailed on September 27, 2022. A second letter will be mailed once a remedy is established. Owners may contact Gillig's customer service at 1-510-264-5073 or 1-800-735-1500.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.

We have received Gillig's proposed owner notification letter and have approved it for distribution.

Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Gillig, LLC's contact for this recall will be Michelle Rice who may be reached by email at michelle.rice@dot.gov. We look forward to working with you.

Sincerely,



Alex Ansley
Chief, Recall Management Division
Office of Defects Investigation
Enforcement