CATERPILLAR* Previous Screen	Service Information Syste	Shutdown SIS
		Welcome: chrismk2
 Product: NO EQUIPMENT SELECTED Model: NO EQUIPMENT SELECTED Configuration: NO EQUIPMENT SELECTED 		
Service Magazine 2013/09/16		
Media Number -SEPD1665-00	Publication Date -16/09/2013	Date Updated -16/09/2013

i05440669

CT11 and CT13 Valve Cover Bolts {7000}

SMCS - 7000

On Highway Truck:

CT660 (S/N: TGA1-UP; TGD1-UP; TJD1-UP; TEJ1-UP; TRK1-UP; TKL1-UP; TEM1-UP; TEP1-UP; TGR1-UP; TGS1-UP; TJS1-UP; TGT1-UP; TGW1-UP; TSW1-UP; TEY1-UP; TSY1-UP; TGZ1-UP)

The valve covers on the CT11 and CT13 engines contain bolts that have different lengths.




Illustration 1

g03433317

- (1) Quantity: 10, 33 mm (1.3 inch) bolts on the drivers side of the engine
- (2) Quantity: 8, 27.5 mm (1.1 inch) bolts on the passenger side

On the right side of the engine (passenger side) there will be eight bolts (2). The remaining ten bolts (1) from the center of the cover to the left side of the engine (driver's side).

Copyright 1993 - 2013 Caterpillar Inc. All Rights Reserved. Private Network For SIS Licensees. Wed Oct 2 17:59:44 CDT 2013 chrismk2