GPOP - Issue Review System

Part Number: RL108213A\$, 52108213A\$

Part Description: NAG1 (5A580) Valve Body

Issue As per Warranty Bulletin D-13-22, please use R2108213A\$ valve body for all

Description: Warranty (W), Mopar (M) and Mopar Vehicle Protection (F) claims.~

Assembly also includes Filter (52108325AA) and Gasket (52108332AA).~

Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquires. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.