

Subject:

Market:

Difficult To Adjust LCD Display Clock

USA

Service Category:

Vehicle Interior

Section:

Meter/Gauge/Display

Applicability:

12-13MY Venza

APPLICABLE VEHICLES

2012-2013

Venza

CONDITION

Some customers may complain that they are unable to or have difficulty understanding how to adjust the LCD display clock.

RECOMMENDATIONS

This issue is currently under investigation. Please contact Technical Assistance (TAS) to discuss diagnostic details on any vehicles identified matching the condition described in this document.

