GPOP - Issue Review System

Part Number: 68206429A\$, 68206430A\$, 68206431A\$

Part Description: Pad, Seat Cushion

Issue Before replacing the above part(s), please call the Micah Straub (engineer) at cell **Description:** (248) 613-2478. Engineering is gathering information regarding this system. If no

response in 15 minutes, proceed with repair.~

Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.