

- ATTENTION:**
- GENERAL MANAGER
 - PARTS MANAGER
 - CLAIMS PERSONNEL
 - SERVICE MANAGER

IMPORTANT - All Service Personnel Should Read and Initial in the boxes provided, right.

© 2016 Subaru of America, Inc. All rights reserved.



QUALITY DRIVEN® SERVICE

SERVICE BULLETIN

APPLICABILITY: 2010-2014MY Legacy and Outback

NUMBER: 06-53-16

SUBJECT: Rattling Sound from Front Brake Caliper Support

DATE: 05/09/16

INTRODUCTION:

This bulletin announces a design change to the front brake caliper supports to address customer concerns of a rattling sound heard while driving. The change involves a reduction in the amount of clearance between the caliper support mounting bolt holes and the mounting bolts.

NOTE: This information is applicable to models using 16" front brakes ONLY.

Description	Part Number
SUPPORT RH	26225AG120
SUPPORT LH	26225AG130
SUPPORT F DISK BRAKE RH	26225AJ000
SUPPORT F DISK BRAKE LH	26225AJ010

SERVICE PROCEDURE / INFORMATION:

After confirming the support is the root cause of the condition, replace the affected side following the service procedure in the applicable Service Manual.

WARRANTY / CLAIM INFORMATION:

For vehicles within the Basic New Car Limited Warranty period or covered by a Subaru Added Security Classic or Gold plan, this repair may be submitted using the following claim information:

Labor Description	Labor Operation #	Failure Code	Labor Time
ONE FRONT BRAKE CALIPER SUPPORT R&R	A511-303	QAR-25	0.3
BOTH FRONT BRAKE CALIPER SUPPORTS R&R	A511-314		0.5

IMPORTANT REMINDERS:

- SOA strongly discourages the printing and/or local storage of service information as previously released information and electronic publications may be updated at any time.
- Always check for any open recalls or campaigns anytime a vehicle is in for servicing.
- Always refer to STIS for the latest service information before performing any repairs.

CAUTION: VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.

Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.

SUBARU OF AMERICA, INC. IS ISO 14001 COMPLIANT

ISO 14001 is the international standard for excellence in Environmental Management Systems. Please recycle or dispose of automotive products in a manner that is friendly to our environment and in accordance with all local, state and federal laws and regulations.