



Quality Inspection Request

Radiator – Engine Cooling

Suspect Part Identification

Part number: 68143886AA.

Manufacturing date code location:-

Date code on part pictured:

1606A: DDDYS:

160th day of 2016 : Shift A (First shift)

(Not suspect)



Suspect parts: All parts with manufactured codes before: 2745, any shift i.e. A, B, & C.

All before 274th day of 2015, (October 1st 2015). I.E.: 2735, 2725, 2715... 0015.