

March 30, 2016

MY13 LD, LX

GPOP - Issue Review System

Part Number: R8149638A\$

Part Description: 8-speed transmission

Issue Description: Verify two (2) 6102212AA alignment dowel pins are installed in the 4x4 adaptor prior to transmission installation.

~
Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquires. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
~