

5/4/2016

MY 14, 15

LD, LX, WK, WD

GPOP - Issue Review System

Part Number: 55113664A\$, 55113665A\$, 55113660A\$, 55113661A\$

Part Description: Side door Upper and lower hinge, All side doors

Issue Description: If the vehicle is in for side door hinge noise on WK and WD (Jeep Grand Cherokee and Dodge Durango) or LD/LX (Dodge Charger and Chrysler 300) 2014, 2015, 2016 MY 0 to 36,000 miles, FCA is looking to gather information prior to repairing the vehicle. Please contact Kevin Murphree via Cell Phone (248) 613-3417.~

If the dealership is within the Metro Detroit Area, Kevin would like to analyze the vehicle in person prior to repair.~

~

~

Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
