



## Quality Inspection Request 52121050AA – Brake Rotor Correct and Suspect Part Identification

Suspect parts have packaging date code of 2015/05/12.

## **Correct Part Identification**



## **Suspect Part Identification**



Correct part has 8 Bolted holes, black paint on top hat and vented brake plate on the rotor.

Suspect part has 5 bolted holes on the rotor.