

**On-car analysis list from March 7th, 2017  
please contact VW Helpline before attempting repair**

	<b>Models</b>	<b>MY</b>	<b>Engine</b>	<b>Transmission</b>	<b>Topic</b>	<b>Customer Complaint</b>
<b>Powertrain</b>	Passat	14-17	1.8T (CPKA/CPRA)	All	MIL-on P2407	MIL-on fault P2407 in the ECM <b>(untouched vehicles)</b>
	Touareg	16-17	All	All	Coolant leak from coolant pump	Coolant leak from the coolant pump <b>(untouched vehicles)</b>
	Passat, Beetle, Jetta	14-17	1.8T (CPKA/CPRA)	All	Oil pressure warning with P164D	Oil pressure warning with P164D in the ECM <b>(Must have fault in the ECM)</b> <b>(Must have oil in the connector of the oil pressure switch)</b>
<b>Chassis</b>	Jetta	16-17	All	All	Rear Brake Caliper	Rear brake noise, dragging, excessive dust <b>(untouched vehicles)</b>
	Jetta	17	All	All	Brake Hissing	Hissing noise when pressing the brake pedal <b>(untouched vehicles)</b>
	GTI	16-17	All	6 Spd Standard	Clutch pedal squeak	Customer states the clutch pedal squeaks when operated <b>(after VIN 3VWY77AU0GM068470)</b>
<b>Body</b>	Passat	16	All	All	Instrument Panel Noise	Instrument panel noise <b>(untouched vehicles after VIN HC011431)</b>
	Passat	16 - 17	All	All	Trunk latch (release) inoperative	Trunk latch will not release with key fob, button in the door, on the trunk or with easy open feature (foot release).
	Golf/GTI	16 - 17	All	All	Sunroof Motor Loss Basic Settings	Sunroof controls malfunctioning
	Golf/GTI	17	All	All	Sunroof Squeak/Rattle	Sunroof squeaks/rattles with the sunroof in closed position
	Passat	16-17	All	All	Door Noise	Door(s) noise <b>(untouched vehicles after VIN GC052150 )</b>