

Subject		Market
HVAC Drain Tube Blocked/Clogged		USA
Service Category	Section	
Vehicle Interior	Heating/Air Conditioning	
Applicability		
Various Lexus Models and Model Years		

APPLICABLE VEHICLES

2015-2019	RC F	2018-2019	LS500
2015-2019	RC350	2015-2019	NX300H
2010-2015	IS250C	2008-2010	SC430
2008-2016	LS600H	2012	LFA
2018-2019	LC500	2016-2019	GS300
2018-2019	LC500H	2006-2015	IS250
2008	RX400H	2016-2019	IS300
2016-2017	GS200T	2015-2017	NX200T
2018-2019	LS500H	2008-2011	GS460
2008-2011, 2013-2018	GS450H	2010-2012	HS250H
2013-2019	ES300H	2019	GS F
2008-2019	ES350	2019	UX200
2008-2017	LS460	2019	UX250H
2008-2009	GX470	2010-2019	GX460
2016-2019	RC300	2010-2019	RX450H
2018-2019	NX300	2008-2011, 2013-2019	GS350
2011-2018	CT200H	2010-2019	IS350
2008-2019	RX350	2016-2017	IS200T
2010-2015	IS350C	2008-2014	IS F
2016-2017	RC200T	2008-2011, 2013-2019	LX570

CONDITION

HVAC drain tube is found to blocked/clogged.

RECOMMENDATIONS

Before the drain tube is cleared of the blockage, use a Borescope to look inside the drain tube to evaluate the cause of the blockage. Using the Borescope, please take detailed photographs of the blockage and submit a DPR including the pictures. Also, include photographs of the material after it has been removed.

LINK REFERENCES

This Tech Tip does not contain any link references