File in Section:

Bulletin No.: PIE0480A

Date: November, 2018

ENGINEERING INFORMATION

Subject: Engineering Information – Exhaust Smell in Vehicle, Exhaust Noise Heard Coming

from Under Hood, Check Engine Light On, DTCs P0442, P0496, P0455, P0430 and

P0420 Set

This PI has been revised to end the need for information from the field. Please discard PIE0480.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to	Eligille.	
Cadillac	XTS	2013	2018			Equipped with	
Chevrolet	Impala					3.6L Engine	

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

Version	2
Modified	Released August 14, 2018 Revised November 09, 2018 – Ended the need for further information from the field.