


Spot Corrosion on B-Pillar and/or C-Pillar

Service

Category Vehicle Exterior

Section Paint/Coatings Market USA



Applicability

YEAR(S)	MODEL(S)	ADDITIONAL INFORMATION
2012 - 2015	Tacoma	WMI(s): 3TM, 5TF

OBSOLETE NOTICE

March 29, 2019: This bulletin is now obsolete. Please see T-SB-0035-19.