

**On-car analysis list from June 14th, 2019**  
**please contact VW Helpline before attempting repair**

	Models	MY	Engine	Transmission	Topic	Customer Complaint
<b>Powertrain</b>	Jetta	19	All	All	Heat Shield	Customer states noise from heat shield <b>(untouched vehicles)</b>
	Jetta	19	1.4T (DGXA / DJXA)	All	MIL-on P0496	Customer states MIL-on <b>(Must have P0496 in the ECM)</b>
	Jetta	19	1.4T (DGXA / DJXA)	All	MIL-on 1429 and/or P0556	Customer states MIL-on <b>(Must have 1429 and/or P0556 in the ECM and vacuum pump inoperative)</b>
	Jetta	19	All	All	MIL-on P0197	Customer states MIL-on <b>(Must have P0197 in the ECM with wiring damaged at oil level sensor)</b>
	Jetta	19	1.4T (DGXA / DJXA)	All	MIL-on P0133	Customer states MIL-on <b>(Must have P0133 in the ECM)</b>
	ATLAS	19	3.6 (CDVC)	All	MIL-on P0116	Customer states MIL-on <b>(Must have P1558 in the ECM)</b> <b>(untouched vehicles)</b>
	Tiguan LWB	19	All	All	MIL-on P11AD, P11AE, P11AF	Customer states MIL-on <b>(Must have one or all of P11AD, P11AE, P11AF )</b> <b>(untouched vehicles)</b>
<b>Body</b>	Tiguan LWB	18-19	All	All	Sunshade Binding	Customer states the sunshade is binding/tearing/separating <b>(untouched vehicles)</b>
	Golf	16	All	All	Front Window(s) Noise or Inop	The front window regulator(s) exhibiting noise, shutter, binding, or is inoperative. <b>(untouched vehicles)</b>
	Tiguan LWB	18-19	All	All	Windshield Distorted/Warped	Customer states front windshield is distorted/warped <b>(untouched vehicles)</b>
	Jetta	19	All	All	Door Module	Customer states "door warning light" on dash and/or locks, mirrors or window functions inoperative <b>(untouched vehicles)</b>
<b>Electrical</b>	Jetta, Beetle, Beetle Convertible, Tiguan, Golf, Golf SportWagen	19	All	All	Horn Inoperative	Customer states horn is inoperative or does not sound correct <b>(untouched vehicles)</b>
	Passat	17-19	All	All	Airbag light on B200000	Customer states airbag light on <b>(Must have fault B200000 with symptom code 16712596)</b> <b>(untouched vehicles)</b>