



# Technical Journal

TITLE:

**SPA Condensation water drops in around pedals area**

<b>REF NO:</b> TJ 34650.1.0	<b>ISSUING DEPARTMENT:</b> Technical Service	<b>CAR MARKET:</b> United States and Canada	
<b>PARTNER:</b> 3 US 7510 Volvo Car USA		<b>ISSUE DATE:</b> 2019-06-24	<b>STATUS DATE:</b> 2019-06-26
<b>FUNC GROUP:</b> 8700	<b>FUNC DESC:</b> Air conditioning unit	Page 1 of 2	

“Right first time in Time”

## Attachment

File Name	File Size
<a href="#">Drain Hose VCC-516946-2 en-US.pdf</a>	11.021 MB
<a href="#">Drain Hose VCC-516946-4 en-US.pdf</a>	11.099 MB
<a href="#">Drain Hose VCC-516947-2 en-US.pdf</a>	9.7413 MB
<a href="#">Drain Hose VCC-516947-3 en-US.pdf</a>	9.8032 MB

## Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
2XX							2016-9999		0000001-9999999	201505-999952

## CSC Customer Symptom Codes

Code	Description
N8	Climate control system/A/C water leaks/condensation

## VST Operation Number

VST Operation Number	Description
98732-2	Drain hose adjust acc. to TJ34650

## DTC Diagnostic Trouble Codes



## Text

### DESCRIPTION:

If water/condensation droplets from the A/C evaporator occur around the driver's side foot well area, follow advice under Service.

### SERVICE:

Service kit, Part Nr. 32130501 is introduced as a service solution.

Follow method in the attached TJ Instructions,

VCC-516946-2 for 256 (16-) early version

VCC-516946-4 for 234 (17-),235 (17-),236 (17-) early version

VCC-516947-2 for 246 (18-),256 (16-) late version

VCC-516947-3 for 224 (19-),225 (19-), 227 (19-), 234 (18-), 235 (18-), 236 (18-), 238 (18-) late version

Warranty claim info:

To get warranty claim accepted for a job described in this TJ, please use following data:

VST OP Number: 98732-2

### VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 8700.

**To view TJ attachments, click on the provided links. This TJ has four attachments.**