

## **Technical Service Bulletin**

| CASE REMOVAL & INSTALLATION |                     |                        | No:   | TSB-19-11-003        |
|-----------------------------|---------------------|------------------------|-------|----------------------|
|                             |                     |                        | DATE: | July 2019            |
|                             |                     |                        | MODE  | L: 2014-16 Outlander |
| CIRCULATE TO:               | [] GENERAL MANAGER  | [] PARTS MANAGER       |       | [ X ] TECHNICIAN     |
| [X] SERVICE ADVISOR         | [X] SERVICE MANAGER | [X] WARRANTY PROCESSOR |       | [] SALES MANAGER     |

## PURPOSE

This TSB updates the Engine Section of the affected Service Manuals, to revise the oil pan and timing chain case removal and installation procedure.

## **AFFECTED VEHICLES**

• 2014 - 2016 Outlander

## AFFECTED SERVICE MANUAL

• 2014 - 2016 Outlander Service Manual, Group 11-Engine

Page 2 of 2 TSB-19-11-003

Please make the indicated changes to the 2014 - 2016 Outlander Service Manual, Group 11-Engine -> 11B-Engine Overhaul <2.4L Engine> -> Oil Pan and Timing Chain Case.

