

## FT4662 Cracked Driver Stationary and Sliding Glass

Technical writer name

Devanand

Manual section 3

First Level Parts		
Material	Part Number	QTY
MV122 Mullion retrofit Kit	N8910149	1

Nb hours Level 1	0.50 h
------------------	--------

MQR	7621-1893
-----	-----------

Disposal of parts		
Removed parts are:		When the retained check box is checked, the parts must be retained and returned in accordance with the usual warranty procedure to be reimbursed.
Discarded	Retained	
-	-	

Client	Order	Road numbers		VIN		QTY	Lang.	Customer	Target market	Plant	Config moteur	Model	NR	R1
New York City Transit - New York	LA76	8508	8633	L82J9J9776924	L82J8K9777144	125	E	NYCT	US	PLB	TD	40	X	
New York City Transit - New York	LB29	5531	5566	S92J9J9776687	S92J6J9776873	36	E	NYCT	US	PLB	TD	60	X	
New York City Transit - New York	LB78	8526	8526	L82J3K9776984	L82J3K9776984	1	E	NYCT	US	PLB	TD	40	X	
New York City Transit - New York	LB99	5567	5602	S92J2J9776935	S92J5K9777000	36	E	NYCT	US	PLB	TD	60	X	
New York City Transit - New York	LC32	8634	8754	L82JXK9777145	L82J5K9777277	121	E	NYCT	US	PLB	TD	40	X	