

Passenger side outside mirror glass adjusts itself at random at ignition on/off

Topic number	LI72.40-P-058875
Version	1
Design group	72.40 Door control
Date	04-10-2014
Validity	MODEL 205.0 without CODE P49/221/222/234/275/873/877/885/889
Reason for change	Remedy adapted
Reason for block	

Complaint:

When the ignition is switched on (circuit 15 on) or after the ignition is switched off (circuit 15 off), the front passenger mirror moves at random for approx. 2 seconds.

Cause:

Software error in door control unit (passenger side).

Remedy:

Perform SCN coding of door control unit (passenger side) using Xentry Diagnostics (XD) (Xentry Diagnostics => DCU-Fx => Adaptations => Configuration => SCN coding).

Symptoms
Body / Door/Flap / Outside mirror / Mirror/Mirror adjustment / Mirror glass adjusts itself

Work units				
Op. no.	Operation text	Time	Damage code	Note
			72220 ER	

Validity		
Vehicle	Engine	Transmission
205.002	*	*
205.003	*	*
205.004	*	*
205.008	*	*
205.009	*	*
205.012	*	*

205.036	*	*
205.037	*	*
205.040	*	*
205.041	*	*
205.042	*	*
205.045	*	*
205.049	*	*
205.066	*	*

Full model designation breakdown		
Vehicle	Engine	Transmission
205.002	651.921	716.754
205.002	651.921	722.908
205.002	651.921	725.011
205.003	651.921	716.754
205.003	651.921	722.908
205.003	651.921	725.011
205.004	651.921	716.754
205.004	651.921	722.908
205.004	651.921	725.011
205.008	651.921	716.754
205.008	651.921	722.908
205.008	651.921	725.011
205.009	651.921	716.754
205.009	651.921	722.965
205.012	651.921	716.754
205.012	651.921	724.208
205.012	651.921	725.011
205.036	626.951	716.700
205.036	626.951	722.993
205.037	626.951	716.700
205.037	626.951	722.993
205.040	274.910	716.702
205.040	274.910	722.995
205.040	274.910	725.011
205.041	274.910	716.702
205.041	274.910	722.995
205.041	274.910	725.011
205.042	274.920	716.702
205.042	274.920	722.995
205.042	274.920	725.011
205.045	274.920	716.702

205.045	274.920	722.995
205.045	274.920	725.011
205.049	274.920	716.702
205.049	274.920	722.969
205.066	276.823	722.961
205.066	276.823	725.041