BAHAMAS, BOLIVIA, BELIZE, CANADA, CHILE, TAIWAN, COLOMBIA, COSTA RICA, DOMINICAN REPUBLIC, ECUADOR, EL

SALVADOR, TRINIDAD AND TOBAGO, UNITED STATES, URUGUAY, VENEZUELA, Countries: ARUBA, NICARAGUA, PERU, PUERTO RICO, ID:

Curação, GUAM, GUATEMALA, GUYANA, HAITI, HONDURAS, JAMAICA, KOREA,

SOUTH KOREA, PANAMA

Availability: ISIS, Bus ISIS, FleetISIS, IsSIR Maior

BUS BODY System:

Current Language:

English

Other Français, Español, Languages:

2466 Viewed:

Revision: 5

Created: 5/1/2008

Document IK2200073

Last 10/11/2019 Modified:

Author:

Brandon

Akridge

Less Info

Hide Details Copy Link

œ

Knowledge Base

Copy Relative Link

Bookmark

Add to Favorites

Print

Coding Information

Provide Feedback





Title: Bus Body Entry Door Switch, LH Panel Mounted

Applies To: CS, IC, FE and RE Bus Models

CHANGE LOG

Please refer to the change log text box below for recent changes to this article:

10/11/2019 --Added part numbers for new switches past Aug 2010

DESCRIPTION

When replacing a two or three position entrance door switch in a CS, IC, FE or RE bus, the following information will assist in obtaining the correct part number.


- · Entry Door Switch, LH Panel Mounted
- · CS, IC, FE and RE Models

SERVICE PARTS INFORMATION

Kit Description	Part Number	Manufacturer	Notes
2 Position, Electric Door	452977001	Square D	Pre-2006
3 Position, Electric Door	452978001	Square D	Pre-2006
2 Position, Electric Door	2222674C1	Cutler Hammer	2006 to Aug 2010
3 Position, Electric Door	2222675C1	Cutler Hammer	2006 to Aug 2010
2 Position, Air Door	441440001	Square D	Pre-2006
3 Position, Air Door	441441001	Square D	Pre-2006
2 Position, Air Door	2222672C1	Cutler Hammer	2006 to Aug 2010

3 Position, Air Door	2222673C1	Cutler Hammer	2006 to Aug 2010
2 Position, All Doors	//1//5/56/1	Carling Technologies	Aug 2010 to current
3 Position, All Doors		Carling Technologies	Aug 2010 to current

For additional assistance in determining the required switch for a specific unit, refer to International Parts Catalog for your specific VIN, under Group 21.



WARRANTY INFORMATION

Warranty Claim Coding:

Refer to the Warranty Coding Manual for Group and Noun Codes.

Standard Repair Time(s):

Refer to the **SRT Manual** for Repair Times

Note: Adjustments are only covered under warranty for the first 90 days in service.

OTHER RESOURCES

Master Service Information Site

☆ Hide Details	Feedback Information			
	Viewed: 2465			
	Helpful: 113			
	Not Helpful: 169			
No Feedback Found				

Copyright © 2019 Navistar, Inc.