



## REMOVAL - PULLOUT COUNTER TOP EXTENSION

<b>Bulletin Type:</b>	INC	<b>Publication Date:</b>	March 2020
<b>Bulletin #(s):</b>	20-007	<b>Make(s):</b>	EMBARK, REATTA, ENTEGR A COACH
<b>Job Code(s):</b>	N/A	<b>Model(s):</b>	VARIOUS
<b>Flat Rate(s):</b>	N/A	<b>Model Year(s):</b>	MY2009 TO 2021

<b>Incident:</b>	ANY REPAIR WORK REQUIRING REMOVAL OF PULLOUT CABINET EXTENSION DRAWERS.
<b>Affected Units:</b>	MAKES AND MODELS WITH PULLOUT CABINET EXTENSION
<b>Parts Kit:</b>	<b>Parts Kit #: NA</b>
	<b>Parts Kit Contents: NA</b>
<b>Misc. Tools &amp; Supplies:</b>	SCREW GUN, #2 SQUARE HEAD BIT.
<b>Parts Return Information:</b>	NA

## INSTRUCTIONS

1. The pullout counter top extension can be removed by accessing the screws under the bottom third drawer.
2. Remove as many of the pullout drawers as necessary to remove the screws inside the bottom of the cabinet securing the cabinet to the metal sliding plate.



3. Remove the screws at the bottom of the cabinet securing the cabinet to the metal sliding plate.



View from inside the cabinet with drawer removed.



View from under the cabinet.

*Jayco's sole obligation under our limited warranty is to repair or replace defective materials and/or workmanship deemed our responsibility as determined by Jayco in our sole discretion. Jayco reserves the right to use new and/or remanufactured parts or materials of similar quality to complete any work, and to make parts and/or design changes as appropriate without notice to anyone. Jayco designs and/or materials changes are done without obligation to incorporate such changes in previously manufactured product. Jayco makes every reasonable effort to ensure field remedies will not adversely affect performance and/or safety of the unit. This field remedy is not intended to extend to future performance of this RV, or any of its materials, components or parts beyond the standard warranty period. The RV owner's obligation to notify Jayco, or one of its independent, authorized dealers, of a claimed defect does not modify any obligation placed on the RV owner to contact Jayco directly when attempting to pursue remedies under state or federal law. Jan. 2019.*

903 South Main Street • P.O. Box 460 • Middlebury, IN 46540