



Safety Recall and Service Campaign - Technician Certification Requirements

Posted 5/1/2020

IMPORTANT:

Refer to the following matrix to determine the technician certification requirements for each specific Safety Recall or Service Campaign. Special Courses and Additional Requirements are noted in the two columns on the far right. Refer to the Dealer Letter of the specific Safety Recall or Service Campaign for more information.

Safety Recall or Service Campaign	Description	Certification Level Requirements for Service Technicians / Diagnostic Specialists			Special Courses	Additional Requirements
		Certified	Senior	Master		
Safety Recall 20LA01	Certain 2017 RC 200t, IS 200t; 2018-2019 ES 350, GS 300, GS 350, IS 300, IS 350, RC 300, RC 350; Vehicle May Stall During Driving at Higher Speed	✓	✓	✓	LSC19A	
Safety Recall 20LA02	Certain 2020 ES 300h; Certain Engine Blocks Can Cause Engine Failure Leading to Fire Risk		✓	✓		
Special Service Campaign (SSC) 19LC05	Certain 2016-2019 RX 450h; Oil Cooler Pipe	✓	✓	✓	LSC19A	
Safety Recall KLF	Certain 2019 ES 300h, LC 500, LS 500, LS 500h, UX 250h Potential Loss of Power Brake Assist		✓	✓		
Limited Service Campaign (LSC) KLG / CSP 19LE05	Certain 2011-2017 LS, 2013-2016 LS HV, 2011-2017 GS, 2016-2017 GS-F, 2013-2017 GS HV, 2010-2017 IS, 2011-2015 IS-C, 2013-2014 IS-F, 2015-2017 RC, 2015-2017 RC-F, 2011-2017 CT, 2010-2017 RX, 2010-2017 RX HV, 2015-2017 NX, 2015-2017 NX HV, 2013-2017 LX, 2013-2018 GX, 2010-2017 ES, 2013-2017 ES HV Safety Connect System - Vehicle Location Inaccurate	✓	✓	✓	LSC19A	
Safety Recall JLL	Certain 2008-2019 LX 570 Passenger Airbags Could Deactivate	✓	✓	✓	LSC19A	
Safety Recall KLE	Certain 2019 ES350 Driver Knee Airbag Replacement	✓	✓	✓	LSC19A	
Safety Recall KLD	Certain 2019 ES350 Driver Knee Airbag Replacement	✓	✓	✓	LSC19A	
Special Service Campaign (SSC) JLG	Certain 2010 GX 460 Air Injection Pumps and Air Switching Valves	✓	✓	✓	LSC19A	
Safety Recall KLC	Certain 2018 LS 500 & LS 500h Possible Partial Tread Separation of Run-Flat Tires	✓	✓	✓	LSC19A	
Special Service Campaign (SSC) KLA	Certain 2018 GS 350, RC 300, RC 350, IS 300, IS 350, RX 350, RX 350L Engine ECU Software Update	✓	✓	✓	LSC19A	
Safety Recall JSL	Certain 2008-2019 LX 570 Passenger Airbags Could Deactivate	✓	✓	✓	LSC19A	
Safety Recall JLE	Certain 2018 LS 500 Engine ECU Software Update	✓	✓	✓	LSC19A	
Safety Recall JLI/JLJ/JLK	Certain 2007-2012 ES350, 2010-2017 GX460, 2008-2009 ISF, 2006-2012 IS250, 2010-2015 IS250C, 2006-2012 IS350, 2010-2011 IS350C, 2002-2010 SC430 Front Passenger Airbag Inflator Module	✓*	✓*	✓	LSC19A	*36 months Lexus experience and L652 + LSC13B
Special Service Campaign (SSC) JLH	Certain 2018 LS 500/500h, 2018 NX 300/300h, 2018 RX 350L/450hL, 2017-2018 RX 350/450h Intelligent Clearance Sonar (ICS) System Reprogram	✓	✓	✓	LSC19A	
Safety Recall JLF	Certain 2007-2011 GS350, GS450h, 2006-2014 IS350, IS350C Fuel Delivery Pipe	✓	✓	✓	LSC19A	
Safety Recall JLD	Certain 2017 RX 350 Vacuum Pump	✓	✓	✓	LSC19A	
Limited Service Campaign (LSC) JLC	Certain 2017 RX350/450h Safety Connect System		✓	✓		
Safety Recall JLA	Certain 2015-2016 NX300h/200t, 2016 RX350/450h Airbag Sensor	✓*	✓*	✓	LSC19A	*L652
Safety Recall JLB	Certain 2015-2018 RC-F, 2016-2018 GS-F, 2018 LC 500 High Pressure Fuel Pumps	✓	✓	✓	LSC19A	

Safety Recall or Service Campaign	Description	Certification Level Requirements for Service Technicians / Diagnostic Specialists			Special Courses	Additional Requirements
		Certified	Senior	Master		
Safety (Non-Compliance) Recall HLF	Certain 2018 GX 460 Load Carrying Capacity Modification Label	✓	✓	✓	LSC19A	
Safety Recall HLE	Certain 2010 HS 250h HV Transaxle		✓	✓		L071
Safety Recall HLD	Certain 2006 LX 470, 2008-2013 LX 570 Driver or Front Passenger Airbag Assembly			✓		
Safety Recall HLC	Certain 2017 ES 350 Tie Rod Lock Nut Torque		✓	✓		L453
Limited Service Campaign (LSC) HLB	Certain 2017 MY GS 350 AWD Carpet Floor Mat Replacement	✓	✓	✓	LSC19A	
Safety Recall GLG/GLH/HLA	Certain 2006 - 2013 MY IS 250/350, 2008 - 2014 MY IS F, 2007-2012 ES 350, 2010-2017 GX 460, 2010-2015 IS Convertible Takata Air Bag	✓*	✓*	✓	LSC19A	*36 months Lexus experience and L652 + LSC13B
Limited Service Campaign (LSC) GLM	Certain 2015 RC350/RC-F & Certain 2014-2015 IS 250/350 Rear Wheel Arch Corrosion		✓	✓		
Safety Recall GLB	2004-2006 GX 470 & 2003-2006 LX 470 SRS ECU		✓	✓		
Special Service Campaign (SSC) GLP	Certain 2015-2017 MY NX 200t & NX 300h ABS Software Update	✓	✓	✓	LSC19A	
Limited Service Campaign (LSC) GLL	Certain 2016 MY RX 350 & RX 450h Power Rear Hatch ECU	✓	✓	✓	LSC19A	
Safety Recall GLJ	2011-2012 MY CT 200h Curtain Shield Airbag			✓		
Safety Recall GLK	Supplement to CLE - 2010 Model Year HS250h Reinspection Required - Rear Lower Suspension Arm No. 1		✓	✓		L453
Limited Service Campaign (LSC) GLI	Certain 2016 MY RC 300 AWD & RC 350 AWD Carpet Floor Mat Replacement	✓	✓	✓	LSC19A	
Special Service Campaign (SSC) GLE	Certain 2016 MY RX 450h Fuel Tank Ring Replacement		✓	✓		
Limited Service Campaign (LSC) GLD	Certain 2015 MY GS 350, LS 460 RC 350 and certain 2016 MY GX 460, IS 200t/300/350, NX 200t Safety Connect System		✓	✓		
Safety Recall GLC	Certain 2016 MY ES 350 & RX 350 Brake Actuator Inspection/Replacement		✓	✓		
Safety Recall GLA	Certain 2016 Model Year RX355, RX400h Driver Knee Airbag Inspection and Replacement		✓	✓		
Special Service Campaign (SSC) FLF	Certain 2010 - 2012 Model Year HS 250h Vehicles Fuel Pump and Wire Harness Replacement		✓	✓		
Safety Recall FLE	Certain 2013 - 2015 Model Year ES350, ES300h Pre-Collision System		✓	✓		
Safety Recall FLD	Certain 2007 Model Year RX400h Powertrain and Hybrid ECU Software Update	✓*	✓	✓	LSC19A	*L623
Safety Recall FLC	2015 Model Year NX 200t Vehicles Brake Actuator		✓*	✓*		*With Self-Paced Module HL511A
Limited Service Campaign (LSC) FLB	Certain 2010 Model Year RX450h Vehicles Oxygen Sensor Replacement		✓	✓		
Limited Service Campaign (LSC) FLA	2013 Model Year GS350 and GS450h Vehicles Front Passenger Supplemental Restraint System		✓	✓		L652
Safety Recall ELG	For Areas of High Absolute Humidity 2002 through 2005 Model Year SC 430 Vehicles Front Passenger Air Bag Inflator Module	✓*	✓*	✓	LSC19A	*36 months Lexus experience and L652 + LSC13B
Safety Recall ELF	Certain 2007-2011 GS350, 2007-2011 IS350, 2010 IS350C (2GR-FE Engine), Certain 2006 GS300 (3GR-FE Engine), Certain 2006-2010 IS250, 2010 IS250C (4GR-FSE Engine), Certain 2007-2010 LS460 (1UR-FSE Engine), 2008-2011 LS600hL (2UR-FSE Engine), Certain 2008-2011 GS460 (1UR-FSE Engine), Certain 2007-2011 GS450h (2GR-FSE Engine), Certain 2008-2011 IS-F (2UR-GSE) Vehicles Fuel Pressure Sensor Gasket	✓	✓	✓	LSC19A	
Limited Service Campaign (LSC) ELE	Certain 2008 through 2012 Model Year IS F Vehicles Engine Cooling Fans		✓	✓		
Safety Recall ELD	Certain 2015 MY RX 350 Vehicles Equipped with 2GR-FE Engine Potential Fuel Delivery Pipe Leak	✓	✓	✓	LSC19A	
Safety Recall ELB	2013 GS 350 Vehicles Brake Pedal Load Sensing Switch		✓	✓		

Safety Recall or Service Campaign	Description	Certification Level Requirements for Service Technicians / Diagnostic Specialists			Special Courses	Additional Requirements
		Certified	Senior	Master		
Safety Recall ELA	2012-2013 RX350 Brake Actuator Reprogramming	✓	✓	✓	LSC19A	
Safety Recall DSC	2002-2004 SC430 Vehicles Front Passenger Air Bag Inflator Module	✓*	✓*	✓	LSC19A	*36 months Lexus experience and L652 + LSC13B
Safety Recall DLG	2006-2011 IS350, 2010-2011 IS350C, 2007-2011 GS350 2GR-FSE Intake VVT Actuator Gear		✓	✓		
Safety Recall DLF	2006-2008 RX400h Intelligent Power Module (IPM) Replacement		✓	✓		L071
Safety Recall DLD	2010 Model Year HS250h Vehicles Brake Booster Pump Assembly (Accumulator)					*It up to the Dealer's discretion as to which technicians can perform this Safety Recall.
Safety Recall DLC	2002-2003 SC430 Front Passenger Airbag Inflator Module	✓*	✓*	✓	LSC19A	*36 months Lexus experience and L652 + LSC13B
Safety Recall CSE	Supplement to CLE - 2010 Model Year HS250h Reinspection Required - Rear Lower Suspension Arm No. 1		✓	✓		L453
SSC BSL	2010 RX350, 2008 - 2010 LX570 Smart Stop Technology	✓	✓	✓	LSC19A	
Limited Service Campaign (LSC) 9LH	9LH Extension; 2007-2009 RX 350 and 2007-2008 ES 350 Vehicles 2GR-FE (V6) Engine VVT-i Oil Hose Replacement		✓	✓		