

GPOP - Issue Review System

Part Number: 68042365A\$, 68042370A\$

Part Description: CABLE, Latch Release, Track to Recliner, Left

Issue Description: Prior to replacing for any kind of damage or functional concern , please take photos of the condition and/ or issue with seat cable before disassembly, Please email pictures of cable including part number to FCA Redacted Content; please include dealer contact information for follow up.

If no response in 15 minutes, proceed with repair.

~
Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
