

## Latest Vehicle Concern Fixes

### BODY



#### Outer Door Seal Adrift

18 – 20MY E-PACE

##### Customer Voice:

- A customer may report a wind noise or that the door seal is coming loose.

##### Technical Description:

- The door seal may be coming loose from it's retaining clips or incorrectly positioned.

##### Status:

- Engineering is currently investigating this concern and request your support by reporting any door seal concern via EPQR.
- Please include pictures of the door seal and any customer verbatim regarding the symptom experienced.

