

---

## Warranty Information

---

92A, 970, 95B

**2000**

---

## Timing Chain Cover Repairs

---

This bulletin is replacing bulletin 1901, dated November 25, 2019.

---

Model Line: Cayenne - V6T & V8 engine  
Panamera - V6T & V8 engine  
Macan - V6T engine

Model Year: **Cayenne, Panamera (2011 - 2017), Macan (2015 - 2018)**

Information: If an oil leak is identified from the timing chain cover and it has been found that any part on the timing cover has failed, then the engine must be removed and the entire timing chain cover resealed per the WM instructions.

### Documentation Requirements



**Active leak #1 overview of oil on engine**

---

Warranty Information


---

92A, 970, 95B

2000

---

Information  
(continued):



Location and source of oil leak



A picture of the location and source of oil leak with engine  
clearly removed *is required*

Warranty Information

92A, 970, 95B

2000

Invoicing: For invoicing and documentation using PCSS, the cause of failure must be encoded as follows:

Location (FES5)	15330	Chain Housing Cover
Damage Type	5043	Oil Leak

**Suggested Labor Operations**

**Macan S:**

- 10011940 - R&I engine
- 37342790 - Unflange & flange transmission
- 10012790 - Unflange & flange engine
- 10011360 - Engine fasten
- 15331990 - R&I chain housing cover
- 87031750 - Refrigerant drain & fill
- 19381790 - Coolant drain and fill
- 44950300 - Alignment
- 44951553 - Alignment
- 46161902 - Remove brake-disc air guide
- 45600550 - Adjust steering angle sensor
- 27851550 - Adjust measuring sensor\*
- 96382550 - Adjust front camera\*

**Macan GTS:**

- 10011940 - R&I engine
- 37342790 - Unflange & flange transmission
- 10012790 - Unflange & flange engine
- 10011360 - Engine fasten
- 15331990 - R&I chain housing cover
- 87031750 - Refrigerant drain & fill
- 19381790 - Coolant drain and fill
- 44950300 - Alignment
- 44951553 - Alignment
- 46161902 - Remove brake-disc air guide
- 45600550 - Adjust steering angle sensor
- 27851550 - Adjust measuring sensor\*
- 96382550 - Adjust front camera\*

**Macan Turbo:**

- 10011940 - R&I engine
- 37342790 - Unflange & flange transmission
- 10012790 - Unflange & flange engine
- 10011360 - Engine fasten
- 15331990 - R&I chain housing cover
- 87031750 - Refrigerant drain & fill
- 19381790 - Coolant drain and fill
- 44950300 - Alignment
- 44951553 - Alignment
- 46161902 - Remove brake-disc air guide
- 45600550 - Adjust steering angle sensor
- 27851550 - Adjust measuring sensor\*
- 96382550 - Adjust front camera\*

\*If vehicle is equipped with respective option then additional labors may apply.

---

## Warranty Information

---

92A, 970, 95B

**2000**

---

**Cayenne S:**

10011940 – R&I Engine (without PDCC) **Or** 10011941 (with PDCC)

10012790 – Unflange Engine (without PDCC) **Or** 10012791 (with PDCC)

15331990 – Chain Housing Cover

87031750 – Refrigerant drained & filled

43030750 – PDCC Bled (with PDCC only)

44950300 – Alignment

44951553 – Alignment