



Technical Journal

TITLE:

Noise from fuel pipe against the body floor

REF NO: TJ 35586.1.0	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada	
PARTNER: 3 US 7510 Volvo Car USA		ISSUE DATE: 2020-07-07	STATUS DATE: 2020-07-13
FUNC GROUP: 2340	FUNC DESC: Fuel tank, fuel lines, evaporator system	Page 1 of 3	

“Right first time in Time”

Attachment

File Name	File Size
TJ35586.MOV	5.6051 MB
TJ35586.pdf	0.2682 MB

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
224	BK	B1LPHEV					2020-2020		-	201940-202006
224	BR	B1FPHEV					2020-2020		-	201940-202006
225	BK	B1LPHEV					2020-2020		-	201940-202006
225	BR	B1FPHEV					2020-2020		-	201940-202006
235	BR	B1FPHEV					2020-2020		-	201940-202006
238	BR	B1FPHEV					2020-2020		-	201940-202006
246	BK	B1LPHEV					2020-2020		-	201940-202006
246	BR	B1FPHEV					2020-2020		-	201940-202006
256	BK	B1LPHEV					2020-2020		-	201940-202006
256	BR	B1FPHEV					2020-2020		-	201940-202006



CSC Customer Symptom Codes

Code	Description
C4	Complete vehicle/Unusual noise/While driving
F2	Driving/Unusual noise/During acceleration
ZE	Idling/Unusual noise
ZO	Rear seat/Squeak/rattle

VST Operation Number

VST Operation Number	Description
99926-2	General reimbursement acc. to TJ

DESCRIPTION:

Only vehicles with steel fuel tank.

If a noise can be heard from the rear of the vehicle when combustion engine is running (ICE), follow “service”. See attached movie.

SERVICE:

Mount a sound absorber P/N 9203622 on the fuel pipe, see attached picture.

Warranty claim info:

To get warranty claim accepted for a job described in this TJ, please use following data:

VST OP number: 99926-2

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area “Vehicle Report” and sub concern area “Support not needed”, use function group 2340.

To view TJ attachment continue to the next page. This TJ has one attachment and one [sound file](#).



V O L V O

Sound absorber P/N 9203622



TJ35586