

FT4950 Engine door hinge becoming loose NYCT

Technical writer name
Devanand

Manual section 02

First Level Parts (100% of 411 vehicles)		
Material	Part Number	QTY
HINGE ENGINE DOOR ASSEMBLY	N100866	2
NUT LOCK HFR M6 SS A2 70	N87917	4
BOLT M6X30 SS A2 DIN933	N29152	4
WASHER FLAT M6 SS HVY D734	N30730	4

Nb hours Level 1 0.5 hr **MQR** 7621-2009

Disposal of parts		
Removed parts are:		When the retained check box is checked, the parts must be retained and returned in accordance with the usual warranty procedure to be reimbursed.
Discarded	Retained	
X	-	

Shop Supply (100% of 411 vehicles)		
Material	Part Number	QTY
THREAD LOCKER BLUE	9985283	1.6 Oz

Note:
9985283 (THREAD LOCKER BLUE)
 1 ea = 50ml
 1.6 Oz (47.31 ml) / Bus
 20550 ml for 411 buses
 411 Bottles for the entire campaign

Client	Order	Road numbers		VIN		QTY	Lang.	Customer	Target market	Plant	Config moteur	Model	NR	R1
New York City Transit - New York	L959	5443	5443	S92J0H9776118	S92J0H9776118	1	E	NYCT	US	PLB	TD	60	x	
New York City Transit - New York	LB59	5444	5484	S92J7H9776195	S92J6H9776379	41	E	NYCT	US	PLB	TD	60	x	
New York City Transit - New York	LA23	5485	5530	S92J5J9776380	S92J6J9776517	46	E	NYCT	US	PLB	TD	60	x	
New York City Transit - New York	LB29	5531	5566	S92J9J9776687	S92J6J9776873	36	E	NYCT	US	PLB	TD	60	x	
New York City Transit - New York	LB99	5567	5602	S92J2J9776935	S92J5K9777000	36	E	NYCT	US	PLB	TD	60	x	
New York City Transit - New York	LA73	8504	8507	L82J8J9776445	L82J8J9776476	4	E	NYCT	US	PLB	TD	40	x	
New York City Transit - New York	LA76	8508	8633	L82J9J9776924	L82J8K9777144	125	E	NYCT	US	PLB	TD	40	x	
New York City Transit - New York	LC32	8634	8754	L82JXK9777145	L82J5K9777277	121	E	NYCT	US	PLB	TD	40	x	
New York City Transit - New York	LB78	8526	8526	L82J3K9776984	L82J3K9776984	1	E	NYCT	US	PLB	TD	40	x	