

Newmar Corporation

PO Box 30
Nappanee, IN 46550



WHEN YOU KNOW THE DIFFERENCE.

RSB 556
Oct. 21, 2020

NHTSA #20V 509
TC #2020-393

RECALL SERVICE BULLETIN

AFFECTED MODELS

2018 :: Essex, New Aire
2019 :: Ventana, Dutch Star, New Aire, Mountain Aire, London Aire, Essex

DESCRIPTION

Daimler Trucks North America LLC, has decided that a defect relating to motor vehicle safety exists in specific motorhomes built on Freightliner chassis (NHTSA # 20V 485). In response, Newmar Corporation is issuing NHTSA Recall # 20V 509, TC # 2020-393.

ISSUE

On certain motorhomes built on Freightliner Chassis, the instrument panel (IP) controller illumination may not meet the FMVSS 101 requirements. A display that does not dim to a level barely discernable (as required in FMVSS 101) might create glare that could reduce the driver's visibility of the road, thus increasing the risk of a crash.

UNITS AFFECTED

Refer to the attached population list for specific VIN numbers supplied by DTNA for the coaches that are affected.

CORRECTIVE ACTION

Vehicles will be inspected for software versions. In some cases, the vehicle will receive a software update or a processor and software update. Repairs will be performed by Daimler Trucks North America authorized service facilities. DTNA will provide work instructions and any necessary parts to complete the recall procedure.

CUSTOMER ACTION

Contact Daimler Trucks North America at 1-800-547-0712 to locate a Qualified Service Center near you. If you need further assistance, contact the Newmar service department at 1-800-731-8300. A brand specialist will assist you in scheduling an appointment to have this repair completed.

DEALER ACTION

Contact the Freightliner Customer Support Center at 1-800-FTL-HELP (1-800-385-4357), and follow the prompts, or visit <https://freightliner.com/dealer-search/> to locate an authorized DTNA service center to schedule and perform the recall near you. If you need assistance contacting DTNA, contact your Newmar Service Account Manager.

NOTE

Newmar will not be authorizing this repair. DTNA will authorize and schedule this repair.

IMPORTANT: Please read this bulletin in its entirety prior to beginning any diagnosis or repairs.

NOTICE: Any technical information published in this bulletin is intended for use only by a qualified, Newmar-authorized service technician. Newmar is not responsible for the misuse of this information.



WHEN YOU KNOW THE DIFFERENCE

NEWMAR CORPORATION

NEWMARCORP.COM

Date: September 22, 2020
Re: Newmar Corporation – Motor Vehicle Recall Notification

Subject: Recall Campaign No.: 20V 509

This notice is sent to you as a Newmar Dealer in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Newmar Corporation has decided that a defect, which relates to motor vehicle safety, exists in specific Newmar recreational vehicles.

The National Traffic and Motor Vehicle Safety Act requires that each vehicle, which is subject to a recall campaign of this type, must be satisfactorily repaired within a reasonable time after the owner has tendered it for repair. A failure to adequately repair within 60 days after tender of a vehicle is prima facie evidence of failure to repair within a reasonable time. To avoid providing these problematic solutions, every effort must be made to promptly schedule an appointment with each owner and to repair their vehicle as soon as possible. Vehicle owners are being notified of this recall. If the condition is not remedied within a reasonable time, they are instructed on how to contact the National Highway Traffic Safety Administration.

REASON FOR THIS RECALL

In response to notification from Daimler Trucks North America LLC, Newmar Corporation has decided that a defect, which relates to motor vehicle safety, exists in specific motorhomes built on Freightliner Chassis.

On certain motorhomes built on Freightliner Chassis, the instrument panel (IP) controller illumination may not meet the FMVSS 101 requirements. A display that does not dim to a level barely discernable as required in FMVSS 101, might create glare that could reduce certain driver's visibility of the road, thus increasing the risk of a crash. Vehicles will be inspected for software versions, and based on the software version, vehicles will receive a software update in some cases the vehicle will receive a processor and software update. Repairs will be performed by Daimler Trucks North America authorized service facilities. Estimated time for repair is 0.5 hrs.

The motorhomes require immediate service. Continued use poses a potential safety hazard.

DEALER CAMPAIGN RESPONSIBILITY

Dealers are to provide to all customers/owner vehicles the service of completing this campaign at no charge to the customer/owner regardless of vehicle age, vehicle mileage, or ownership at the time of repair.

REPAIR PROCEDURE

DTNA will provide the work instructions.

If you should have any questions please contact your service account manager direct or the Newmar service department at: 1-866-290-5371.

Thank you for your cooperation.

Sincerely,

Newmar Corporation



WHEN YOU KNOW THE DIFFERENCE

NEWMAR CORPORATION

NEWMARCORP.COM

IMPORTANT SAFETY RECALL

This notice applies to your vehicle VIN. # _____

Name

Address

City, State Zip code

Date: September 22, 2020

Motor Vehicle Recall Notification - Recall Campaign No. 20V 509

Dear Valued Customer:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

REASON FOR THIS RECALL

Newmar Corporation has decided that a defect, which relates to motor vehicle safety, exists in specific motorhomes built on Freightliner Chassis. This recall is the result of information provided to us by Daimler Trucks North America LLC.

On certain motorhomes built on Freightliner Chassis, the instrument panel (IP) controller illumination may not meet the FMVSS 101 requirements. A display that does not dim to a level barely discernable as required in FMVSS 101, might create glare that could reduce certain driver’s visibility of the road, thus increasing the risk of a crash. Vehicles will be inspected for software versions, and based on the software version, vehicles will receive a software update in some cases the vehicle will receive a processor and software update. Repairs will be performed by Daimler Trucks North America authorized service facilities. Estimated time for repair is 0.5 hrs.

The motorhomes require immediate service. Continued use poses a potential safety hazard.

The Safety Risk

A display that does not dim to a level barely discernable as required in FMVSS 101, might create glare that could reduce certain driver’s visibility of the road, thus increasing the risk of a crash.

WHAT WE WILL DO

DTNA will provide owners of all affected motorhomes a remedy for the potential defect at no charge for parts or labor. Vehicles will be inspected for software versions, and based on the software version, vehicles will receive a software update in some cases the vehicle will receive a processor and software update.

WHAT YOU NEED TO DO

As this defect does affect motor vehicle safety, it is recommended that you call **Daimler Trucks North America @ 800-547-0712** to locate a Qualified Service Center near you. If you need further assistance contact the Newmar service department immediately at 1-800-731-8300. An associate will assist you in making an appointment to have this repair completed.

Federal regulations require that any vehicle lessor receiving this recall notification must forward a copy of this notice to the lessee within ten days.

If you have had the repair performed before receiving this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy. For additional information, contact Newmar Corporation at:

Service Department
Newmar Corporation
355 N Delaware St
Nappanee, IN 46550-0030

Authorized Chassis Service Facility, are best equipped to obtain parts and provide service to ensure your vehicle is corrected as promptly as possible. HOWEVER, if you take your vehicle to your Authorized Chassis Service Facility on the scheduled date and this condition is not remedied on that date or within five days; please contact the Newmar Corporation Customer Service Department at 1-800-731-8300. You may also submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Ave., SE., Washington DC 20590; or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov>.

If you no longer own this vehicle, please furnish us the complete name and address of the person or dealership you sold or traded your vehicle to. Thank you for your cooperation.

Your safety and satisfaction with your Newmar product is important to us and we regret any inconvenience to you.

Sincerely,

Newmar Corporation



Date: September 22, 2020
Re: Newmar Corporation – Motor Vehicle Recall Notification

Subject: Recall Campaign No.: # 2020-393

This notice is sent to you as a Newmar Dealer in accordance with the requirements of the *Canada Motor Vehicle Safety Act*. Newmar Corporation has decided that a defect, which relates to motor vehicle safety, exists in specific Newmar recreational vehicles.

Each vehicle, which is subject to a recall campaign of this type, must be satisfactorily repaired within a reasonable time after the owner has tendered it for repair. A failure to adequately repair within 60 days after tender of a vehicle is prima facie evidence of failure to repair within a reasonable time. To avoid providing these problematic solutions, every effort must be made to promptly schedule an appointment with each owner and to repair their vehicle as soon as possible. Vehicle owners are being notified of this recall. If the condition is not remedied within a reasonable time, they are instructed to contact Transport Canada.

REASON FOR THIS RECALL

Newmar Corporation has decided that a defect, which relates to motor vehicle safety, exists in specific motorhomes built on Freightliner chassis. This recall is the result of information provided to us by Daimler Trucks North America LLC.

Issue:

On certain motorhomes built on a Freightliner chassis, the driver may not be able to dim the lights on the instrument panel to a low level. As a result, light from the instrument panel could cause glare while driving at night. Canadian regulations require that the instrument panel lights can be dimmed to a lower level.

Safety Risk:

Glare from bright instrument panel lights could reduce visibility and increase the risk of a crash.

Corrective Actions:

Vehicles will be inspected for software versions, and based on the software version, vehicles will receive a software update in some cases the vehicle will receive a processor and software update. Repairs will be performed by Daimler Trucks North America authorized service facilities. Estimated time for repair is 0.5 hrs. This recall applies to certain Newmar 2018-2019 New Aire; 2019 Dutch Star; 2019 London Aire; 2019 Mountain Aire motorhomes.

The motorhomes require immediate service. Continued use poses a potential safety hazard.

DEALER CAMPAIGN RESPONSIBILITY

Dealers are to provide to all customers/owner vehicles the service of completing this campaign at no charge to the customer/owner regardless of vehicle age, vehicle mileage, or ownership at the time of repair.

REPAIR PROCEDURE

DTNA will provide the work instructions. Vehicles will be inspected for software versions, and based on the software version, vehicles will receive a software update in some cases the vehicle will receive a processor and software update.

If you should have any questions please contact your service account manager direct or the Newmar service department at: 1-866-290-5371.

Thank you for your cooperation.

Sincerely, Newmar Corporation



WHEN YOU KNOW THE DIFFERENCE

VIN#
make, model, model year
Name
Address
City, State Zip code

Date: September 22, 2020
Motor Vehicle Recall Notification - Recall Campaign No. 2020-393

Dear Valued Customer:

This notice is sent to you in accordance with the requirements of the *Canada Motor Vehicle Safety Act*.

This is to inform you that your vehicle may contain a defect that could affect the safety of a person.

REASON FOR THIS RECALL

Newmar Corporation has decided that a defect, which relates to motor vehicle safety, exists in specific motorhomes built on Freightliner chassis. This recall is the result of information provided to us by Daimler Trucks North America LLC.

Issue:

On certain motorhomes built on a Freightliner chassis, the driver may not be able to dim the lights on the instrument panel to a low level. As a result, light from the instrument panel could cause glare while driving at night. Canadian regulations require that the instrument panel lights can be dimmed to a lower level.

Safety Risk:

Glare from bright instrument panel lights could reduce visibility and increase the risk of a crash.

Corrective Actions:

Vehicles will be inspected for software versions, and based on the software version, vehicles will receive a software update in some cases the vehicle will receive a processor and software update. Repairs will be performed by Daimler Trucks North America authorized service facilities. Estimated time for repair is 0.5 hrs.

The motorhomes require immediate service. Continued use poses a potential safety hazard.

WHAT WE WILL DO

DTNA will provide owners of all affected motorhomes a remedy for the potential defect at no charge for parts or labor. Vehicles will be inspected for software versions, and based on the software version, vehicles will receive a software update in some cases the vehicle will receive a processor and software update.

WHAT YOU NEED TO DO

As this defect does affect motor vehicle safety, it is recommended that you call Daimler Trucks North America @ **800-547-0712** to locate a Qualified Service Center near you. If you need further assistance contact the Newmar service department immediately at 1-800-731-8300. An associate will assist you in making an appointment to have this repair completed.

Federal regulations require that any vehicle lessor receiving this recall notification must forward a copy of this notice to the lessee within ten days.

If you have had the repair performed before receiving this letter, you may be eligible to receive reimbursement for the cost of obtaining a pre-notification remedy. For additional information contact Newmar Corporation at:

Service Department
Newmar Corporation
355 N Delaware St
Nappanee, IN 46550-0030

Authorized Chassis Service Facility, are best equipped to obtain parts and provide service to ensure your vehicle is corrected as promptly as possible. HOWEVER, if you take your vehicle to your Authorized Chassis Service Facility on the scheduled date and this condition is not remedied on that date or within five days; please contact the Newmar Corporation Customer Service Department at 1-800-731-8300.

If you no longer own this vehicle, please furnish us the complete name and address of the person or dealership you sold or traded your vehicle to. Thank you for your cooperation.

Your safety and satisfaction with your Newmar product is important to us and we regret any inconvenience to you.

Sincerely,

Newmar Corporation



WHEN YOU KNOW THE DIFFERENCE

N° VIN
marque, modèle, année du modèle
Name (Nom)
Adresse
Ville, province et code postal

Date : 22 septembre 2020
Avis de rappel de véhicule automobile : campagne de rappel n° 2020-393

Cher client :

Le présent avis vous est envoyé conformément aux exigences de la *Loi sur la sécurité automobile du Canada*.

La présente a pour but de vous informer que votre véhicule est susceptible d'avoir un défaut qui pourrait porter atteinte à la sécurité humaine.

RAISON DE CE RAPPEL

Newmar Corporation a déterminé que certaines autocaravanes construites sur un châssis Freightliner présentaient un défaut lié à la sécurité. Ce rappel fait suite à des informations fournies par Daimler Trucks North America LLC.

Problème :

Le conducteur de certaines autocaravanes construites sur un châssis Freightliner pourrait ne pas être en mesure de baisser la luminosité sur le tableau de bord. En conséquence, la luminosité du tableau de bord pourrait être aveuglante lors de la conduite nocturne. Les réglementations canadiennes exigent que la luminosité du tableau de bord puisse être baissée.

Risque pour la sécurité :

L'aveuglement causé par une luminosité élevée provenant du tableau de bord peut réduire la visibilité et augmenter le risque d'accident.

Mesures correctives :

La version du logiciel des véhicules sera inspectée. Certains véhicules recevront une mise à jour de la version du logiciel et, dans certains cas, une mise à jour du processeur et du logiciel. Les réparations seront effectuées par les centres de réparation autorisés de Daimler Trucks North America. Le temps estimé pour la réparation est de trente minutes.

Les autocaravanes nécessitent une inspection immédiate. Continuer à utiliser ces véhicules sans les faire contrôler constitue un risque potentiel pour la sécurité.

CE QUE NOUS FERONS

DTNA fournira aux propriétaires de toutes les autocaravanes concernées un remède pour le défaut potentiel, sans frais de pièces ou de main-d'œuvre. La version du logiciel des véhicules sera inspectée. Certains véhicules recevront une mise à jour de la version du logiciel et, dans certains cas, une mise à jour du processeur et du logiciel.

CE QUE VOUS DEVEZ FAIRE

Étant donné que ce défaut est lié à la sécurité automobile, il est recommandé d'appeler Daimler Trucks North America en composant le **1 800 547-0712** pour trouver un centre de réparations certifié dans votre région. Pour toute aide supplémentaire, communiquez avec le service technique de Newmar en composant le 1 800 731-8300. Un représentant vous aidera à fixer un rendez-vous afin de faire effectuer cette réparation.

Les réglementations fédérales exigent que tout loueur de véhicule recevant cet avis de rappel en transmette une copie au locataire dans un délai de dix jours.

Si vous avez fait effectuer la réparation avant de recevoir cette lettre, vous pourriez être admissible à un remboursement des frais liés à cette réparation. Pour de plus amples renseignements, veuillez communiquer avec Newmar Corporation :

Service technique
NewMar Corporation
355 N Delaware St
Nappanee, IN 46550-0030

Les centres certifiés d'entretien de châssis sont les mieux équipés pour obtenir des pièces et effectuer la réparation afin que votre véhicule soit réparé le plus rapidement possible. TOUTEFOIS, si vous confiez votre véhicule à votre centre certifié d'entretien de châssis à la date prévue et que la réparation n'est pas effectuée à cette date ou dans un délai de cinq jours, veuillez communiquer avec le service à la clientèle de Newmar Corporation en composant le 1 800 731-8300.

Si vous n'êtes plus propriétaire de ce véhicule, veuillez nous fournir le nom et l'adresse de la personne ou du concessionnaire à qui vous avez vendu ou échangé le véhicule. Nous vous remercions de votre coopération.

Votre sécurité et votre satisfaction à l'égard des produits Newmar sont importantes pour nous. Nous vous prions de nous excuser pour tous désagréments que cette situation a pu vous causer.

Cordialement,

Newmar Corporation

Prod#	VIN Number	Year	Brand	Type	Floor	Chassis	Date In	Date Off
USA Units								
414675	4UZACHD29JCJT4751	2019	VT	DP	3709	FL	5/15/2019	5/24/2019
501571	4UZFG0KCY2514	2019	LA	DP	4576	FL	1/31/2018	2/7/2018
501583	4UZFG0KCKH5495	2019	LA	DP	4576	FL	5/8/2018	5/17/2018
501589	4UZFG8KCKP0999	2019	LA	DP	4551	FL	5/29/2018	6/6/2018
501591	4UZFG2KCKW0629	2019	LA	DP	4579	FL	8/22/2018	8/30/2018
501592	4UZFG9KCLM7430	2019	LA	DP	4576	FL	1/15/2019	1/21/2019
501593	4UZFG6KCKR5271	2019	LA	DP	4576	FL	6/15/2018	6/25/2018
501594	4UZFG7KCLM7443	2019	LA	DP	4551	FL	4/25/2019	5/3/2019
501600	4UZFGXKCKV7381	2019	LA	DP	4543	FL	8/9/2018	8/17/2018
501601	4UZFG1KCKU9217	2019	LA	DP	4551	FL	7/12/2018	7/20/2018
501602	4UZFG7KCKY2111	2019	LA	DP	4579	FL	10/16/2018	10/23/2018
501603	4UZFG2KCLM7432	2019	LA	DP	4543	FL	1/17/2019	1/24/2019
501605	4UZFG4KCKX9053	2019	LA	DP	4579	FL	10/11/2018	10/18/2018
501606	4UZFG9KCKY2112	2019	LA	DP	4551	FL	10/17/2018	10/24/2018
501607	4UZFG8KCKU4841	2019	LA	DP	4551	FL	7/9/2018	7/17/2018
501612	4UZFG2KCLM7429	2019	LA	DP	4579	FL	1/16/2019	1/23/2019
501613	4UZFG0KCKV2402	2019	LA	DP	4543	FL	7/25/2018	8/1/2018
501618	4UZFG5KCLM7439	2019	LA	DP	4543	FL	3/5/2019	3/12/2019
501624	4UZFG9KCKP1000	2019	LA	DP	4551	FL	6/5/2018	6/12/2018
501628	4UZFG4KCKV2404	2019	LA	DP	4535	FL	9/6/2018	9/13/2018
501633	4UZFG0KCKX9051	2019	LA	DP	4576	FL	9/13/2018	9/20/2018
501641	4UZFG9KCLM7427	2019	LA	DP	4543	FL	1/8/2019	1/15/2019
501642	4UZFG1KCLM7437	2019	LA	DP	4551	FL	3/21/2019	3/29/2019
501644	4UZFG9KCLM7444	2019	LA	DP	4551	FL	5/9/2019	5/16/2019
501646	4UZFG1KCLM7440	2019	LA	DP	4551	FL	4/5/2019	4/12/2019
501648	4UZFG5KCKP8428	2019	LA	DP	4579	FL	6/6/2018	6/14/2018
501652	4UZFG2KCKV2403	2019	LA	DP	4533	FL	8/20/2018	8/28/2018
501655	4UZFG5KCLE9946	2019	LA	DP	4534	FL	10/29/2018	11/5/2018
501660	4UZFGXKCLH6611	2019	LA	DP	4533	FL	11/16/2018	11/27/2018
501662	4UZFG2KCLL7306	2019	LA	DP	4551	FL	12/17/2018	1/8/2019
501664	4UZFG8KCLJ4371	2019	LA	DP	4551	FL	11/21/2018	12/3/2018
501665	4UZFG4KCLM7433	2019	LA	DP	4579	FL	2/12/2019	2/20/2019
501670	4UZFG0KCLJ1075	2019	LA	DP	4533	FL	11/19/2018	11/28/2018
501671	4UZFG0KCLM7428	2019	LA	DP	4550	FL	1/9/2019	1/15/2019
501675	4UZFG0KCLM7431	2019	LA	DP	4551	FL	2/28/2019	3/7/2019
501676	4UZFGXKCLM7436	2019	LA	DP	4551	FL	3/1/2019	3/8/2019
501679	4UZFG6KCLM7434	2019	LA	DP	4551	FL	2/15/2019	2/22/2019
501681	4UZFG3KCLM7438	2019	LA	DP	4551	FL	3/11/2019	3/18/2019
501683	4UZFG3KCLM7441	2019	LA	DP	4579	FL	3/25/2019	4/1/2019
501684	4UZFG8KCLM7435	2019	LA	DP	4551	FL	4/10/2019	4/18/2019
501685	4UZFG1KCLV8566	2019	LA	DP	4543	FL	5/1/2019	5/8/2019
501687	4UZFG5KCLM7442	2019	LA	DP	4551	FL	4/12/2019	4/22/2019
501691	4UZFG3KCLV8567	2019	LA	DP	4551	FL	5/15/2019	5/22/2019
607268	4UZCHF3KCY2518	2019	DS	DP	4018	FL	2/19/2018	2/27/2018
607269	4UZACHFE0KCY2521	2019	DS	DP	3717	FL	2/21/2018	2/28/2018
607298	4UZCHF1KCY2520	2019	DS	DP	4369	FL	3/21/2018	3/28/2018
607324	4UZCHF1KCKH5503	2019	DS	DP	4328	FL	5/17/2018	5/24/2018
607330	4UZCHF8KCKP8421	2019	DS	DP	4369	FL	6/4/2018	6/12/2018

Prod#	VIN Number	Year	Brand	Type	Floor	Chassis	Date In	Date Off
607334	4UZFCHFE4KCKX9047	2019	DS	DP	4310	FL	9/7/2018	9/13/2018
607336	4UZFCHFE2KCKS5469	2019	DS	DP	4018	FL	6/25/2018	7/11/2018
607337	4UZACHFE9KCKS5463	2019	DS	DP	3736	FL	6/18/2018	6/25/2018
607358	4UZFCHFE3KCKT1488	2019	DS	DP	4018	FL	7/9/2018	7/17/2018
607359	4UZFCHFE8KCKT4273	2019	DS	DP	4018	FL	7/10/2018	7/17/2018
607362	4UZFCHFE8KCKU9212	2019	DS	DP	4363	FL	8/6/2018	8/14/2018
607365	4UZACHFE8KCKV7322	2019	DS	DP	3736	FL	8/13/2018	8/21/2018
607366	4UZACHFEXKCKR5263	2019	DS	DP	3736	FL	6/14/2018	6/22/2018
607367	4UZFCHFE2KCKV2395	2019	DS	DP	4310	FL	8/13/2018	8/21/2018
607368	4UZFCHFEXKCKU9213	2019	DS	DP	4310	FL	8/7/2018	8/14/2018
607372	4UZFCHFE8KCKX9049	2019	DS	DP	4326	FL	9/19/2018	9/26/2018
607373	4UZFCHFE1KCLG5220	2019	DS	DP	4369	FL	10/30/2018	11/6/2018
607376	4UZFCHFE5KCKP8425	2019	DS	DP	4369	FL	6/12/2018	6/19/2018
607378	4UZFCHFE9KCKS5467	2019	DS	DP	4369	FL	7/18/2018	7/25/2018
607380	4UZFCHFE3KCKT4276	2019	DS	DP	4369	FL	7/18/2018	7/26/2018
607382	4UZFCHFE1KCKT1490	2019	DS	DP	4369	FL	6/27/2018	7/12/2018
607383	4UZFCHFE7KCKT1493	2019	DS	DP	4369	FL	7/31/2018	8/7/2018
607386	4UZFCHFE2KCKV2400	2019	DS	DP	4369	FL	7/23/2018	7/31/2018
607387	4UZFCHFE5KCKT8085	2019	DS	DP	4369	FL	7/24/2018	7/31/2018
607391	4UZFCHFE0KCKS5468	2019	DS	DP	4018	FL	6/22/2018	7/10/2018
607392	4UZFCHFEXKCKT4274	2019	DS	DP	4018	FL	7/11/2018	7/18/2018
607396	4UZFCHFE9KCKV2393	2019	DS	DP	4018	FL	8/8/2018	8/16/2018
607398	4UZFCHFE8KCKU4835	2019	DS	DP	4369	FL	7/27/2018	8/6/2018
607399	4UZFCHFE1KCKT8083	2019	DS	DP	4369	FL	7/24/2018	8/1/2018
607400	4UZFCHFE8KCKR5266	2019	DS	DP	4363	FL	6/12/2018	6/20/2018
607403	4UZFCHFE5KCLM7324	2019	DS	DP	4018	FL	3/25/2019	4/1/2019
607405	4UZFCHFE2KCLM7362	2019	DS	DP	4369	FL	3/5/2019	3/13/2019
607406	4UZACHFE6KCLG8267	2019	DS	DP	3736	FL	10/23/2018	10/30/2018
607408	4UZFCHFE4KCKY2109	2019	DS	DP	4018	FL	10/4/2018	10/11/2018
607417	4UZFCHFE0KCLJ4361	2019	DS	DP	4018	FL	11/27/2018	12/4/2018
607421	4UZFCHFE2KCLM7300	2019	DS	DP	4018	FL	12/19/2018	1/10/2019
607424	4UZFCHFE1KCKP0998	2019	DS	DP	4369	FL	5/30/2018	6/7/2018
607425	4UZFCHFE6KCKP8420	2019	DS	DP	4363	FL	6/1/2018	6/8/2018
607429	4UZFCHFE2KCLL7303	2019	DS	DP	4369	FL	2/26/2019	3/5/2019
607433	4UZFCHFE8KCLM7320	2019	DS	DP	4018	FL	3/12/2019	3/19/2019
607441	4UZACHFE7KCKT1486	2019	DS	DP	3717	FL	6/27/2018	7/13/2018
607444	4UZFCHFEXKCKR5267	2019	DS	DP	4369	FL	6/13/2018	6/20/2018
607445	4UZFCHFEXKCKT8082	2019	DS	DP	4369	FL	6/28/2018	7/13/2018
607446	4UZFCHFE1KCKR5268	2019	DS	DP	4369	FL	6/13/2018	6/21/2018
607447	4UZFCHFE8KCKP8418	2019	DS	DP	4018	FL	6/5/2018	6/13/2018
607448	4UZFCHFE5KCKS5465	2019	DS	DP	4369	FL	6/19/2018	6/27/2018
607449	4UZFCHFE4KCKP8416	2019	DS	DP	4018	FL	6/6/2018	6/13/2018
607451	4UZFCHFEXKCKP0997	2019	DS	DP	4363	FL	6/6/2018	6/14/2018
607453	4UZFCHFE1KCKP8423	2019	DS	DP	4369	FL	6/7/2018	6/14/2018
607458	4UZFCHFE1KCKT4275	2019	DS	DP	4328	FL	7/18/2018	7/26/2018
607459	4UZFCHFE2KCKU4832	2019	DS	DP	4018	FL	7/19/2018	7/26/2018
607460	4UZFCHFE5KCKT1492	2019	DS	DP	4369	FL	7/11/2018	7/18/2018
607464	4UZFCHFE1KCKU4837	2019	DS	DP	4369	FL	8/1/2018	8/9/2018
607466	4UZFCHFE0KCKV2394	2019	DS	DP	4328	FL	8/14/2018	8/21/2018

Prod#	VIN Number	Year	Brand	Type	Floor	Chassis	Date In	Date Off
607467	4UZFCHF8KCKV2398	2019	DS	DP	4369	FL	8/9/2018	8/16/2018
607481	4UZFCHFEXKCLM7321	2019	DS	DP	4018	FL	3/12/2019	3/19/2019
607482	4UZFCHF5KCLM7369	2019	DS	DP	4362	FL	3/26/2019	4/2/2019
607483	4UZFCHF5KCLE9943	2019	DS	DP	4369	FL	10/16/2018	10/23/2018
607485	4UZFCHF8KCKY4638	2019	DS	DP	4369	FL	10/1/2018	10/8/2018
607489	4UZFCHF0KCLJ1072	2019	DS	DP	4369	FL	11/20/2018	11/29/2018
607490	4UZFCHF2KCLM7359	2019	DS	DP	4369	FL	1/14/2019	1/21/2019
607492	4UZFCHF0KCLM7358	2019	DS	DP	4328	FL	1/9/2019	1/16/2019
607495	4UZFCHF2KCLJ4362	2019	DS	DP	4018	FL	11/20/2018	11/29/2018
607499	4UZFCHFEXKCLG5586	2019	DS	DP	4369	FL	11/13/2018	11/20/2018
607524	4UZFCHF7KCLE9944	2019	DS	DP	4369	FL	10/23/2018	10/30/2018
607526	4UZFCHF9KCLG5580	2019	DS	DP	4369	FL	11/6/2018	11/13/2018
607548	4UZFCHF6KCLM7378	2019	DS	DP	4310	FL	4/23/2019	4/30/2019
607552	4UZFCHFEXKCLM7352	2019	DS	DP	4369	FL	1/16/2019	1/23/2019
607563	4UZFCHF3KCLG5574	2019	DS	DP	4362	FL	10/30/2018	11/6/2018
607564	4UZFCHF9KCLG5577	2019	DS	DP	4369	FL	10/30/2018	11/6/2018
607565	4UZACHFE0KCLV8564	2019	DS	DP	3717	FL	5/3/2019	5/10/2019
607568	4UZFCHF1KCLM7319	2019	DS	DP	4018	FL	3/1/2019	3/8/2019
607571	4UZFCHFEXKCLG5216	2019	DS	DP	4310	FL	10/23/2018	10/31/2018
607575	4UZFCHF1KCLL3551	2019	DS	DP	4369	FL	12/20/2018	1/10/2019
607576	4UZFCHF4KCLM7380	2019	DS	DP	4369	FL	4/17/2019	4/25/2019
607577	4UZFCHF2KCLG5582	2019	DS	DP	4369	FL	11/6/2018	11/13/2018
607579	4UZFCHF7KCLM7373	2019	DS	DP	4369	FL	4/4/2019	4/11/2019
607589	4UZFCHFEXKCLM7383	2019	DS	DP	4326	FL	4/30/2019	5/7/2019
607592	4UZFCHF1KCLJ9522	2019	DS	DP	4369	FL	1/18/2019	1/25/2019
607597	4UZFCHF1KCLM7384	2019	DS	DP	4369	FL	4/30/2019	5/7/2019
607599	4UZFCHF7KCKY4632	2019	DS	DP	4018	FL	10/11/2018	10/18/2018
607600	4UZACHFE2KCLJ1066	2019	DS	DP	3736	FL	11/20/2018	11/29/2018
607631	4UZACHFE5KCLH6604	2019	DS	DP	3736	FL	11/13/2018	11/21/2018
607633	4UZACHFE7KCKW0616	2019	DS	DP	3736	FL	8/21/2018	8/29/2018
607634	4UZACHFEXKCKW8581	2019	DS	DP	3736	FL	8/30/2018	9/7/2018
607637	4UZFCHF2KCKW0626	2019	DS	DP	4362	FL	8/24/2018	8/31/2018
607638	4UZFCHF4KCKV2401	2019	DS	DP	4362	FL	8/23/2018	8/30/2018
607639	4UZFCHF2KCLJ1073	2019	DS	DP	4363	FL	11/28/2018	12/5/2018
607640	4UZFCHF6KCKY2113	2019	DS	DP	4363	FL	9/27/2018	10/4/2018
607641	4UZFCHF6KCKU9211	2019	DS	DP	4363	FL	8/2/2018	8/9/2018
607642	4UZFCHF0KCKW0625	2019	DS	DP	4363	FL	8/22/2018	9/4/2018
607643	4UZACHFE5KCLM7298	2019	DS	DP	3717	FL	4/9/2019	4/16/2019
607644	4UZACHFE9KCKW0617	2019	DS	DP	3717	FL	8/22/2018	8/30/2018
607645	4UZACHFE3KCKT4272	2019	DS	DP	3717	FL	7/13/2018	7/20/2018
607653	4UZFCHF1KCLM7305	2019	DS	DP	4018	FL	1/17/2019	1/24/2019
607667	4UZFCHF1KCLM2699	2019	DS	DP	4328	FL	2/4/2019	2/11/2019
607702	4UZFCHFEXKCLL3547	2019	DS	DP	4002	FL	2/8/2019	2/15/2019
607704	4UZFCHF5KCKW0622	2019	DS	DP	4002	FL	8/21/2018	8/29/2018
607706	4UZFCHF4KCLM7332	2019	DS	DP	4002	FL	3/27/2019	4/3/2019
607712	4UZFCHF1KCLH6606	2019	DS	DP	4369	FL	11/14/2018	11/21/2018
607713	4UZFCHF4KCKV2396	2019	DS	DP	4369	FL	8/15/2018	8/22/2018
607720	4UZFCHF1KCKW0620	2019	DS	DP	4018	FL	8/15/2018	8/22/2018
607721	4UZFCHF7KCLM7356	2019	DS	DP	4328	FL	1/10/2019	1/17/2019

Prod#	VIN Number	Year	Brand	Type	Floor	Chassis	Date In	Date Off
607723	4UZFCHFE6KCLM7316	2019	DS	DP	4018	FL	3/1/2019	3/8/2019
607726	4UZACHFE2KCLM7291	2019	DS	DP	3736	FL	3/4/2019	3/11/2019
607750	4UZFCHFE4KCKR5264	2019	DS	DP	4018	FL	6/20/2018	6/27/2018
607781	4UZACHFE0KCKV2390	2019	DS	DP	3717	FL	8/2/2018	8/10/2018
607782	4UZFCHFE7KCKV2392	2019	DS	DP	4018	FL	9/7/2018	9/14/2018
607785	4UZFCHFE1KCLM7336	2019	DS	DP	4018	FL	4/17/2019	4/25/2019
607786	4UZFCHFE6KCKX9048	2019	DS	DP	4326	FL	9/7/2018	9/14/2018
607787	4UZFCHFE9KCKY4633	2019	DS	DP	4328	FL	9/14/2018	9/21/2018
607788	4UZFCHFE2KCKX4607	2019	DS	DP	4328	FL	9/10/2018	9/14/2018
607789	4UZFCHFE9KCKX4605	2019	DS	DP	4362	FL	8/30/2018	9/7/2018
607790	4UZFCHFEXKCLM7349	2019	DS	DP	4362	FL	1/25/2019	2/5/2019
607791	4UZFCHFE3KCKP8424	2019	DS	DP	4369	FL	6/8/2018	6/18/2018
607792	4UZFCHFE3KCKR5269	2019	DS	DP	4369	FL	6/21/2018	6/28/2018
607795	4UZFCHFE7KCLL3554	2019	DS	DP	4369	FL	2/4/2019	2/11/2019
607797	4UZACHFEXKCKP8415	2019	DS	DP	3736	FL	6/4/2018	6/11/2018
607804	4UZFCHFE9KCLM7312	2019	DS	DP	4018	FL	2/18/2019	2/25/2019
607805	4UZFCHFE3KCLC9948	2019	DS	DP	4018	FL	9/21/2018	9/28/2018
607808	4UZFCHFE7KCLM7311	2019	DS	DP	4018	FL	1/17/2019	1/24/2019
607809	4UZFCHFE8KCLM7303	2019	DS	DP	4018	FL	12/20/2018	1/11/2019
607810	4UZFCHFE5KCKX4603	2019	DS	DP	4018	FL	9/14/2018	9/21/2018
607811	4UZFCHFE4KCKV7324	2019	DS	DP	4018	FL	8/20/2018	8/28/2018
607812	4UZFCHFE5KCKV2391	2019	DS	DP	4018	FL	8/20/2018	8/28/2018
607814	4UZFCHFE0KCKU4831	2019	DS	DP	4018	FL	7/26/2018	8/2/2018
607815	4UZFCHFEXKCKU4836	2019	DS	DP	4326	FL	7/26/2018	8/2/2018
607816	4UZFCHFEXKCLJ4366	2019	DS	DP	4328	FL	11/28/2018	12/5/2018
607819	4UZFCHFE5KCLG5575	2019	DS	DP	4369	FL	10/24/2018	10/31/2018
607820	4UZFCHFEXKCLJ9521	2019	DS	DP	4369	FL	12/10/2018	12/17/2018
607821	4UZFCHFE4KCKU9210	2019	DS	DP	4369	FL	8/3/2018	8/10/2018
607822	4UZFCHFE3KCLH6607	2019	DS	DP	4369	FL	11/14/2018	11/21/2018
607823	4UZFCHFE3KCKS5464	2019	DS	DP	4369	FL	6/14/2018	6/21/2018
607825	4UZFCHFE7KCLJ1070	2019	DS	DP	4369	FL	11/15/2018	11/26/2018
607830	4UZACHFEXKCLL7298	2019	DS	DP	3736	FL	2/18/2019	2/25/2019
607837	4UZFCHFE1KCLE9941	2019	DS	DP	4002	FL	10/31/2018	11/7/2018
607838	4UZFCHFE2KCLJ4359	2019	DS	DP	4002	FL	11/7/2018	11/14/2018
607839	4UZFCHFE7KCKW0623	2019	DS	DP	4310	FL	8/31/2018	9/10/2018
607841	4UZFCHFE2KCKY4635	2019	DS	DP	4310	FL	9/28/2018	10/5/2018
607843	4UZFCHFEXKCKY4639	2019	DS	DP	4310	FL	10/5/2018	10/12/2018
607845	4UZFCHFE0KCKX4606	2019	DS	DP	4326	FL	8/31/2018	9/10/2018
607850	4UZFCHFE1KCLC9950	2019	DS	DP	4018	FL	9/24/2018	10/1/2018
607853	4UZFCHFE5KCKW0619	2019	DS	DP	4018	FL	9/10/2018	9/17/2018
607855	4UZFCHFEXKCKP8422	2019	DS	DP	4328	FL	6/21/2018	7/9/2018
607858	4UZFCHFE3KCKT8084	2019	DS	DP	4369	FL	6/28/2018	7/16/2018
607860	4UZFCHFE1KCLG5217	2019	DS	DP	4369	FL	10/17/2018	10/24/2018
607863	4UZFCHFE8KCLM7348	2019	DS	DP	4369	FL	12/4/2018	12/11/2018
607864	4UZFCHFE2KCKX9046	2019	DS	DP	4363	FL	8/31/2018	9/10/2018
607867	4UZFCHFE3KCLG5218	2019	DS	DP	4363	FL	10/17/2018	10/25/2018
607869	4UZFCHFE4KCKY4636	2019	DS	DP	4369	FL	9/28/2018	10/5/2018
607870	4UZFCHFE7KCLG5576	2019	DS	DP	4369	FL	10/25/2018	11/1/2018
607873	4UZFCHFE7KCLC9953	2019	DS	DP	4369	FL	10/12/2018	10/19/2018

Prod#	VIN Number	Year	Brand	Type	Floor	Chassis	Date In	Date Off
607875	4UZFCHFE7KCLH6609	2019	DS	DP	4369	FL	10/18/2018	10/25/2018
607876	4UZFCHFE2KCLG5579	2019	DS	DP	4369	FL	11/1/2018	11/8/2018
607878	4UZFCHFE0KCLG5578	2019	DS	DP	4369	FL	10/26/2018	11/2/2018
607879	4UZFCHFE6KCKY4637	2019	DS	DP	4369	FL	10/1/2018	10/5/2018
607892	4UZACHFE1KCLL3544	2019	DS	DP	3717	FL	12/10/2018	12/18/2018
607893	4UZFCHFE0KCLL7302	2019	DS	DP	4328	FL	2/18/2019	2/25/2019
607898	4UZFCHFE6KCLJ4364	2019	DS	DP	4369	FL	11/26/2018	12/3/2018
607901	4UZFCHFE1KCKT1487	2019	DS	DP	4018	FL	6/28/2018	7/16/2018
607903	4UZFCHFE7KCKS5466	2019	DS	DP	4369	FL	6/22/2018	7/9/2018
607904	4UZFCHFE3KCKT1491	2019	DS	DP	4328	FL	7/9/2018	7/16/2018
607930	4UZFCHFE6KCLL7305	2019	DS	DP	4363	FL	12/11/2018	12/19/2018
607931	4UZFCHFE9KCLL7301	2019	DS	DP	4328	FL	1/17/2019	1/24/2019
607932	4UZFCHFE0KCLG5581	2019	DS	DP	4369	FL	11/2/2018	11/9/2018
607936	4UZFCHFE5KCLM7341	2019	DS	DP	4018	FL	5/14/2019	5/21/2019
607937	4UZFCHFE3KCLM7337	2019	DS	DP	4018	FL	4/18/2019	4/26/2019
607938	4UZFCHFE6KCKU9208	2019	DS	DP	4018	FL	7/30/2018	8/7/2018
607939	4UZFCHFEXKCKP8419	2019	DS	DP	4018	FL	6/8/2018	6/15/2018
607940	4UZFCHFE5KCLW2342	2019	DS	DP	4018	FL	5/14/2019	5/22/2019
607941	4UZFCHFE6KCLM7333	2019	DS	DP	4018	FL	4/11/2019	4/18/2019
607944	4UZFCHFE6KCKP8417	2019	DS	DP	4018	FL	6/15/2018	6/22/2018
607945	4UZFCHFE5KCLM7338	2019	DS	DP	4018	FL	4/30/2019	5/8/2019
607948	4UZFCHFEXKCLM7318	2019	DS	DP	4018	FL	3/15/2019	3/22/2019
607949	4UZACHFE3KCLV3858	2019	DS	DP	3736	FL	4/24/2019	5/2/2019
607950	4UZACHFEXKCLM7295	2019	DS	DP	3736	FL	3/28/2019	4/4/2019
607954	4UZFCHFE1KCLM7420	2019	DS	DP	4369	FL	2/25/2019	3/4/2019
607956	4UZACHFE9KCLM7286	2019	DS	DP	3736	FL	1/11/2019	1/18/2019
607958	4UZFCHFE3KCLE9942	2019	DS	DP	4018	FL	10/26/2018	11/2/2018
607961	4UZFCHFE9KCLM7357	2019	DS	DP	4326	FL	1/28/2019	2/6/2019
607963	4UZFCHFE7KCLM7342	2019	DS	DP	4018	FL	5/1/2019	5/8/2019
607964	4UZFCHFE3KCLM7385	2019	DS	DP	4369	FL	5/1/2019	5/8/2019
607966	4UZFCHFE9KCLW2344	2019	DS	DP	4369	FL	5/15/2019	5/22/2019
607968	4UZACHFE8KCLJ1069	2019	DS	DP	3717	FL	12/5/2018	12/12/2018
608005	4UZFCHFE8KCLM7365	2019	DS	DP	4369	FL	3/8/2019	3/15/2019
608023	4UZACHFEXKCKV7323	2019	DS	DP	3717	FL	8/16/2018	8/23/2018
608026	4UZFCHFE7KCLM7339	2019	DS	DP	4018	FL	4/25/2019	5/2/2019
608027	4UZFCHFE8KCKU9209	2019	DS	DP	4018	FL	8/16/2018	8/23/2018
608030	4UZFCHFE8KCLG5585	2019	DS	DP	4369	FL	11/9/2018	11/16/2018
608033	4UZFCHFE3KCLM7340	2019	DS	DP	4018	FL	5/2/2019	5/9/2019
608035	4UZACHFE4KCKV2389	2019	DS	DP	3717	FL	8/10/2018	8/20/2018
608058	4UZACHFE1KCKU9207	2019	DS	DP	3736	FL	7/27/2018	8/6/2018
608059	4UZACHFE5KCLV3859	2019	DS	DP	3717	FL	4/25/2019	5/2/2019
608060	4UZACHFE8KCLG8268	2019	DS	DP	3736	FL	10/26/2018	11/2/2018
608067	4UZFCHFE6KCKR5265	2019	DS	DP	4018	FL	6/15/2018	6/25/2018
608068	4UZFCHFE5KCKT1489	2019	DS	DP	4369	FL	6/25/2018	7/10/2018
608069	4UZFCHFE3KCKN5855	2019	DS	DP	4311	FL	10/10/2018	10/17/2018
608071	4UZFCHFE8KCKW8584	2019	DS	DP	4369	FL	8/28/2018	9/5/2018
608075	4UZFCHFE4KCKU4833	2019	DS	DP	4369	FL	7/20/2018	7/30/2018
608076	4UZFCHFE6KCKU4834	2019	DS	DP	4362	FL	7/26/2018	8/2/2018
608077	4UZFCHFE5KCKT4277	2019	DS	DP	4369	FL	7/23/2018	7/30/2018

Prod#	VIN Number	Year	Brand	Type	Floor	Chassis	Date In	Date Off
608079	4UZFCHFEXKCKW8585	2019	DS	DP	4369	FL	8/29/2018	9/6/2018
608081	4UZFCHFE4KCKW8582	2019	DS	DP	4328	FL	8/29/2018	9/6/2018
608086	4UZACHFE0KCKW0618	2019	DS	DP	3736	FL	9/5/2018	9/12/2018
608087	4UZFCHFE3KCKW0621	2019	DS	DP	4018	FL	8/29/2018	9/6/2018
608092	4UZFCHFE0KCKY4634	2019	DS	DP	4326	FL	9/27/2018	10/3/2018
608093	4UZFCHFE6KCKV2397	2019	DS	DP	4369	FL	8/17/2018	8/24/2018
608094	4UZACHFE8KCKW8580	2019	DS	DP	3717	FL	9/12/2018	9/19/2018
608095	4UZACHFE0KCKX4602	2019	DS	DP	3736	FL	9/18/2018	9/25/2018
608100	4UZACHFE4KCKX9043	2019	DS	DP	3736	FL	9/25/2018	10/2/2018
608101	4UZACHFE2KCKX9042	2019	DS	DP	3717	FL	9/25/2018	10/2/2018
608105	4UZACHFE7KCLH6605	2019	DS	DP	3736	FL	11/16/2018	11/27/2018
608108	4UZFCHFE8KCKY2114	2019	DS	DP	4362	FL	9/26/2018	10/3/2018
608109	4UZFCHFE9KCKX9044	2019	DS	DP	4018	FL	9/26/2018	10/3/2018
608110	4UZFCHFE9KCKW0624	2019	DS	DP	4363	FL	9/24/2018	10/1/2018
608111	4UZACHFE7KCLG5572	2019	DS	DP	3717	FL	10/1/2018	10/8/2018
608112	4UZFCHFE3KCLC9951	2019	DS	DP	4369	FL	10/8/2018	10/15/2018
608113	4UZFCHFE6KCLM7350	2019	DS	DP	4369	FL	1/18/2019	1/25/2019
608115	4UZFCHFE9KCLC9954	2019	DS	DP	4326	FL	10/16/2018	10/23/2018
608118	4UZFCHFE8KCLJ4365	2019	DS	DP	4369	FL	12/7/2018	12/17/2018
608120	4UZFCHFE0KCKX9045	2019	DS	DP	4018	FL	10/3/2018	10/9/2018
608121	4UZFCHFE0KCKY2110	2019	DS	DP	4018	FL	10/3/2018	10/10/2018
608122	4UZFCHFE5KCLC9952	2019	DS	DP	4369	FL	10/9/2018	10/16/2018
608123	4UZFCHFE5KCKY4631	2019	DS	DP	4018	FL	10/9/2018	10/16/2018
608124	4UZFCHFE7KCKX4604	2019	DS	DP	4018	FL	10/2/2018	10/9/2018
608127	4UZFCHFE0KCLM7361	2019	DS	DP	4362	FL	3/6/2019	3/13/2019
608128	4UZFCHFE5KCLG5219	2019	DS	DP	4328	FL	10/19/2018	10/29/2018
608131	4UZFCHFE6KCLG5584	2019	DS	DP	4328	FL	11/9/2018	11/16/2018
608133	4UZFCHFEXKCLM2698	2019	DS	DP	4328	FL	11/27/2018	12/4/2018
608135	4UZFCHFE4KCLM7346	2019	DS	DP	4363	FL	12/11/2018	12/19/2018
608137	4UZFCHFE7KCLJ9525	2019	DS	DP	4362	FL	12/12/2018	12/20/2018
608139	4UZFCHFEXKCLL3550	2019	DS	DP	4362	FL	12/13/2018	12/20/2018
608141	4UZFCHFE3KCLL3552	2019	DS	DP	4362	FL	1/7/2019	1/14/2019
608143	4UZFCHFE9KCLJ1071	2019	DS	DP	4362	FL	11/16/2018	11/27/2018
608145	4UZFCHFE1KCKU9214	2019	DS	DP	4311	FL	12/6/2018	12/13/2018
608147	4UZACHFEXKCLM7281	2019	DS	DP	3736	FL	11/29/2018	12/6/2018
608148	4UZACHFE8KCLL7297	2019	DS	DP	3736	FL	12/13/2018	1/7/2019
608149	4UZACHFE3KCLL3545	2019	DS	DP	3736	FL	12/7/2018	12/14/2018
608150	4UZACHFE4KCLJ1067	2019	DS	DP	3736	FL	11/30/2018	12/7/2018
608151	4UZACHFE6KCLJ1068	2019	DS	DP	3736	FL	11/30/2018	12/7/2018
608152	4UZACHFEXKCLL3543	2019	DS	DP	3736	FL	12/7/2018	12/14/2018
608153	4UZFCHFE2KCLG8269	2019	DS	DP	4018	FL	11/5/2018	11/12/2018
608154	4UZFCHFE4KCLJ4363	2019	DS	DP	4018	FL	11/28/2018	12/5/2018
608155	4UZFCHFE5KCLC9949	2019	DS	DP	4018	FL	10/19/2018	10/26/2018
608157	4UZFCHFE4KCLM7301	2019	DS	DP	4018	FL	1/25/2019	2/5/2019
608159	4UZFCHFE7KCLM7308	2019	DS	DP	4018	FL	2/26/2019	3/5/2019
608163	4UZFCHFE0KCLM7327	2019	DS	DP	4002	FL	3/22/2019	3/29/2019
608165	4UZFCHFE1KCLL3548	2019	DS	DP	4002	FL	2/11/2019	2/18/2019
608169	4UZFCHFE4KCLG5583	2019	DS	DP	4369	FL	11/5/2018	11/12/2018
608170	4UZFCHFE6KCLM7347	2019	DS	DP	4328	FL	11/28/2018	12/5/2018

Prod#	VIN Number	Year	Brand	Type	Floor	Chassis	Date In	Date Off
608172	4UZFCHFEXKCLM7304	2019	DS	DP	4018	FL	1/8/2019	1/15/2019
608175	4UZFCHF7KCKP8426	2019	DS	DP	4311	FL	11/30/2018	12/7/2018
608177	4UZFCHF8KCLL3546	2019	DS	DP	4018	FL	1/21/2019	1/28/2019
608179	4UZFCHF8KCLM7317	2019	DS	DP	4018	FL	3/4/2019	3/12/2019
608181	4UZFCHF5KCLJ9524	2019	DS	DP	4369	FL	12/17/2018	1/8/2019
608184	4UZACHFE1KCLL7299	2019	DS	DP	3736	FL	3/6/2019	3/13/2019
608186	4UZFCHF4KCLJ1074	2019	DS	DP	4328	FL	11/27/2018	12/4/2018
608190	4UZFCHF9KCLJ4360	2019	DS	DP	4002	FL	11/19/2018	11/28/2018
608198	4UZFCHF7KCLM7325	2019	DS	DP	4018	FL	3/18/2019	3/25/2019
608201	4UZFCHF3KCLM7306	2019	DS	DP	4018	FL	1/15/2019	1/22/2019
608203	4UZFCHF7KCLL7300	2019	DS	DP	4369	FL	1/22/2019	1/29/2019
608205	4UZFCHF3KCLM7354	2019	DS	DP	4369	FL	3/6/2019	3/13/2019
608206	4UZFCHF9KCLM7309	2019	DS	DP	4018	FL	1/15/2019	1/22/2019
608212	4UZFCHF6KCLM7302	2019	DS	DP	4018	FL	2/18/2019	2/25/2019
608219	4UZFCHF0KCLM7313	2019	DS	DP	4018	FL	2/20/2019	2/27/2019
608221	4UZFCHF2KCLM7314	2019	DS	DP	4018	FL	2/20/2019	2/27/2019
608222	4UZACHFE0KCLM7287	2019	DS	DP	3736	FL	1/15/2019	1/22/2019
608223	4UZACHFE3KCLM2696	2019	DS	DP	3717	FL	1/16/2019	1/23/2019
608224	4UZFCHF8KCLM2697	2019	DS	DP	4369	FL	1/23/2019	2/1/2019
608225	4UZACHFE1KCLM7282	2019	DS	DP	3736	FL	2/28/2019	3/7/2019
608230	4UZFCHF3KCLJ9523	2019	DS	DP	4362	FL	1/23/2019	2/1/2019
608231	4UZACHFE4KCLM7292	2019	DS	DP	3717	FL	3/19/2019	3/26/2019
608233	4UZFCHF5KCLM7307	2019	DS	DP	4018	FL	1/8/2019	1/15/2019
608234	4UZFCHF5KCLM7355	2019	DS	DP	4369	FL	1/9/2019	1/16/2019
608235	4UZFCHF1KCLM7353	2019	DS	DP	4369	FL	3/6/2019	3/13/2019
608237	4UZFCHFEXKCLM7335	2019	DS	DP	4018	FL	4/11/2019	4/22/2019
608241	4UZACHFE7KCLM7285	2019	DS	DP	3736	FL	2/7/2019	2/14/2019
608243	4UZFCHF8KCLM7351	2019	DS	DP	4369	FL	2/19/2019	2/26/2019
608244	4UZACHFE4KCLM7289	2019	DS	DP	3736	FL	2/21/2019	2/28/2019
608245	4UZFCHF9KCLM7360	2019	DS	DP	4362	FL	2/1/2019	2/8/2019
608248	4UZFCHF1KCLM7322	2019	DS	DP	4054	FL	3/11/2019	3/18/2019
608251	4UZFCHF5KCLM7310	2019	DS	DP	4018	FL	2/21/2019	2/28/2019
608252	4UZACHFE0KCLM7290	2019	DS	DP	3736	FL	2/19/2019	2/26/2019
608257	4UZFCHF4KCLM7377	2019	DS	DP	4363	FL	4/5/2019	4/12/2019
608259	4UZACHFE8KCLM7294	2019	DS	DP	3717	FL	3/19/2019	3/26/2019
608262	4UZFCHF3KCLM7371	2019	DS	DP	4369	FL	3/29/2019	4/8/2019
608263	4UZFCHF3KCLL3549	2019	DS	DP	4054	FL	2/13/2019	2/21/2019
608265	4UZFCHF2KCLM7376	2019	DS	DP	4369	FL	4/5/2019	4/12/2019
608266	4UZFCHF1KCLM7370	2019	DS	DP	4369	FL	3/29/2019	4/5/2019
608268	4UZFCHF6KCLM7364	2019	DS	DP	4369	FL	4/25/2019	5/2/2019
608270	4UZFCHF8KCLM7334	2019	DS	DP	4018	FL	4/12/2019	4/22/2019
608271	4UZFCHF9KCLM7326	2019	DS	DP	4018	FL	4/22/2019	4/29/2019
608272	4UZFCHF6KCLM7381	2019	DS	DP	4369	FL	4/26/2019	5/3/2019
608278	4UZACHFE2KCLM7288	2019	DS	DP	3717	FL	2/12/2019	2/19/2019
608279	4UZFCHF0KCLM7330	2019	DS	DP	4018	FL	4/1/2019	4/8/2019
608283	4UZFCHFEXKCLM7366	2019	DS	DP	4369	FL	3/15/2019	3/22/2019
608285	4UZFCHF5KCLL3553	2019	DS	DP	4369	FL	2/13/2019	2/20/2019
608287	4UZACHFE1KCLM7296	2019	DS	DP	3736	FL	4/1/2019	4/8/2019
608292	4UZFCHF9KCKT1494	2019	DS	DP	4328	FL	2/22/2019	3/1/2019

Prod#	VIN Number	Year	Brand	Type	Floor	Chassis	Date In	Date Off
608293	4UZACHFE1KCLV3860	2019	DS	DP	3736	FL	4/26/2019	5/3/2019
608294	4UZACHFE6KCLM7293	2019	DS	DP	3736	FL	4/5/2019	4/15/2019
608295	4UZFCHFE4KCLM7315	2019	DS	DP	4018	FL	2/28/2019	3/7/2019
608298	4UZFCHFE8KCLM7379	2019	DS	DP	4369	FL	4/15/2019	4/23/2019
608299	4UZFCHFE4KCLM7363	2019	DS	DP	4326	FL	3/7/2019	3/14/2019
608305	4UZFCHFE5KCLM7372	2019	DS	DP	4328	FL	3/12/2019	3/19/2019
608307	4UZFCHFE3KCLM7368	2019	DS	DP	4369	FL	3/25/2019	4/1/2019
608313	4UZFCHFE0KCLM7375	2019	DS	DP	4310	FL	4/17/2019	4/25/2019
608319	4UZFCHFE9KCLM7374	2019	DS	DP	4369	FL	4/22/2019	4/29/2019
608322	4UZFCHFE8KCLM7382	2019	DS	DP	4369	FL	4/29/2019	5/6/2019
608323	4UZACHFE3KCLV3861	2019	DS	DP	3736	FL	5/6/2019	5/13/2019
608325	4UZFCHFE3KCLM7421	2019	DS	DP	4311	FL	4/8/2019	4/16/2019
608326	4UZACHFE7KCLM7299	2019	DS	DP	3717	FL	4/16/2019	4/24/2019
608327	4UZACHFE8KCLV0342	2019	DS	DP	3736	FL	4/16/2019	4/24/2019
608328	4UZFCHFE3KCLM7323	2019	DS	DP	4018	FL	4/26/2019	5/3/2019
608333	4UZFCHFE4KCLW2347	2019	DS	DP	4369	FL	5/7/2019	5/14/2019
608338	4UZFCHFE7KCLW2343	2019	DS	DP	4369	FL	5/16/2019	5/24/2019
608342	4UZFCHFE0KCLW2345	2019	DS	DP	4369	FL	5/16/2019	5/28/2019
608343	4UZACHFE0KCLW2341	2019	DS	DP	3717	FL	5/7/2019	5/14/2019
608352	4UZFCHFE9KCLM7343	2019	DS	DP	4018	FL	5/13/2019	5/20/2019
608353	4UZFCHFE0KCLM7344	2019	DS	DP	4018	FL	5/13/2019	5/21/2019
608355	4UZACHFE2KCLW2339	2019	DS	DP	3736	FL	5/3/2019	5/10/2019
608360	4UZACHFE9KCLW2340	2019	DS	DP	3736	FL	5/17/2019	5/28/2019
710201	4UZACEFCXJCF2482	2018	NA	DP	3343	FL	1/27/2017	2/6/2017
710202	4UZACEFC2JCZZ2602	2018	NA	DP	3343	FL	2/9/2017	2/16/2017
710203	4UZACEFCXJ3685	2018	NA	DP	3341	FL	3/3/2017	3/13/2017
710204	4UZACEFC1JCF2483	2018	NA	DP	3343	FL	2/15/2017	2/23/2017
710205	4UZACEFC8JCN5675	2018	NA	DP	3343	FL	5/19/2017	6/1/2017
710206	4UZACEFC6JCN5674	2018	NA	DP	3341	FL	5/5/2017	5/15/2017
710207	4UZACEFCXJCR8348	2018	NA	DP	3341	FL	7/11/2017	7/19/2017
710208	4UZACEFC7JCS8466	2018	NA	DP	3341	FL	7/31/2017	8/8/2017
710209	4UZACEFC3JCT8413	2018	NA	DP	3343	FL	8/22/2017	8/30/2017
710210	4UZACEFC0JCT1855	2018	NA	DP	3343	FL	8/10/2017	8/18/2017
710211	4UZACEFC9JCT1854	2018	NA	DP	3343	FL	8/7/2017	8/15/2017
710214	4UZACEFC9JCT5533	2018	NA	DP	3341	FL	8/16/2017	8/24/2017
710215	4UZACEFC3JCU5040	2018	NA	DP	3343	FL	8/31/2017	9/11/2017
710219	4UZACEFC5JCU2253	2018	NA	DP	3343	FL	8/28/2017	9/6/2017
710220	4UZACEFC6JCX7061	2018	NA	DP	3343	FL	11/9/2017	11/17/2017
710221	4UZACEFC1JCR8349	2018	NA	DP	3341	FL	7/13/2017	7/21/2017
710222	4UZACEFC3JCJW7510	2018	NA	DP	3343	FL	10/10/2017	10/18/2017
710223	4UZACEFC9JCX3649	2018	NA	DP	3343	FL	10/26/2017	11/3/2017
710224	4UZACEFC9JCJV3675	2018	NA	DP	3343	FL	9/18/2017	9/26/2017
710225	4UZACEFC5KCKJ5753	2018	NA	DP	3341	FL	4/18/2018	4/25/2018
710226	4UZACEFC2JCT1856	2018	NA	DP	3343	FL	8/11/2017	8/18/2017
710227	4UZACEFC2JCU9967	2018	NA	DP	3341	FL	9/11/2017	9/19/2017
710228	4UZACEFC7JCU5042	2018	NA	DP	3343	FL	9/6/2017	9/13/2017
710229	4UZACEFC1JCS6793	2018	NA	DP	3341	FL	7/20/2017	7/28/2017
710231	4UZACEFC1JCJY9456	2018	NA	DP	3343	FL	12/19/2017	1/11/2018
710232	4UZACEFC1JCJW3584	2018	NA	DP	3343	FL	10/3/2017	10/11/2017

Prod#	VIN Number	Year	Brand	Type	Floor	Chassis	Date In	Date Off
710233	4UZACEFC7JCJT8415	2018	NA	DP	3343	FL	8/24/2017	9/1/2017
710234	4UZACEFC0JCJU9966	2018	NA	DP	3343	FL	9/8/2017	9/18/2017
710235	4UZACEFC4JCJZ5560	2018	NA	DP	3343	FL	12/21/2017	1/12/2018
710236	4UZACEFC7JCJV8731	2018	NA	DP	3343	FL	9/27/2017	10/5/2017
710240	4UZACEFC3JCJS6794	2018	NA	DP	3343	FL	7/25/2017	8/2/2017
710243	4UZACEFC9JCJS2426	2018	NA	DP	3341	FL	7/26/2017	8/3/2017
710244	4UZACEFC5JCJR6376	2018	NA	DP	3341	FL	7/17/2017	7/25/2017
710245	4UZACEFC5JCJS6795	2018	NA	DP	3343	FL	7/27/2017	8/4/2017
710246	4UZACEFC6JCJZ3499	2018	NA	DP	3341	FL	12/15/2017	1/9/2018
710247	4UZACEFC2JCJV3677	2018	NA	DP	3343	FL	9/14/2017	9/22/2017
710248	4UZACEFC4JCJX0545	2018	NA	DP	3343	FL	10/18/2017	10/26/2017
710249	4UZACEFC7JCJW7512	2018	NA	DP	3343	FL	10/12/2017	10/20/2017
710250	4UZACEFC3JCJR6375	2018	NA	DP	3341	FL	6/29/2017	7/17/2017
710251	4UZACEFC7JCJS2425	2018	NA	DP	3343	FL	8/3/2017	8/11/2017
710252	4UZACEFC5JCJS2424	2018	NA	DP	3343	FL	7/18/2017	7/26/2017
710253	4UZACEFC9JCJV8732	2018	NA	DP	3343	FL	9/28/2017	10/6/2017
710254	4UZACEFC3JCJW3585	2018	NA	DP	3343	FL	10/5/2017	10/13/2017
710256	4UZACEFC1JCJU2251	2018	NA	DP	3343	FL	9/21/2017	9/29/2017
710257	4UZACEFC2JCJX0544	2018	NA	DP	3341	FL	10/17/2017	10/25/2017
710259	4UZACEFC2JCJX9213	2018	NA	DP	3341	FL	11/1/2017	11/9/2017
710260	4UZACEFC4JCJY4073	2018	NA	DP	3343	FL	11/22/2017	12/1/2017
710261	4UZACEFC7JCJT5532	2018	NA	DP	3343	FL	8/14/2017	8/22/2017
710262	4UZACEFC6JCJX0546	2018	NA	DP	3343	FL	10/20/2017	10/30/2017
710263	4UZACEFC4JCJY2503	2018	NA	DP	3343	FL	11/15/2017	11/27/2017
710264	4UZACEFC2JCJY4072	2018	NA	DP	3341	FL	11/27/2017	12/5/2017
710266	4UZACEFC6JCJY4074	2018	NA	DP	3343	FL	11/29/2017	12/7/2017
710267	4UZACEFC0KCKE8414	2018	NA	DP	3343	FL	3/28/2018	4/6/2018
710268	4UZACEFCXJCKB2535	2018	NA	DP	3343	FL	2/9/2018	2/16/2018
710269	4UZACEFC5JCJY7211	2018	NA	DP	3341	FL	12/5/2017	12/13/2017
710270	4UZACEFC6JCJX9215	2018	NA	DP	3343	FL	11/14/2017	11/22/2017
710271	4UZACEFC7KCKJ5754	2018	NA	DP	3343	FL	4/20/2018	4/27/2018
710272	4UZACEFC6JCJY2504	2018	NA	DP	3341	FL	11/20/2017	11/29/2017
710273	4UZACEFC8JCJY9454	2018	NA	DP	3343	FL	12/7/2017	12/14/2017
710274	4UZACEFC1JCKB2536	2018	NA	DP	3343	FL	2/12/2018	2/20/2018
710275	4UZACEFC5JCJT8414	2018	NA	DP	3343	FL	8/21/2017	8/29/2017
710276	4UZACEFC5JCJU5041	2018	NA	DP	3343	FL	9/1/2017	9/11/2017
710277	4UZACEFC4JCJX9214	2018	NA	DP	3343	FL	11/8/2017	11/16/2017
710278	4UZACEFC2JCJY2502	2018	NA	DP	3343	FL	11/17/2017	11/29/2017
710279	4UZACEFC5JCJV8730	2018	NA	DP	3343	FL	9/25/2017	10/3/2017
710280	4UZACEFC0JCJZ9699	2018	NA	DP	3343	FL	1/18/2018	1/26/2018
710281	4UZACEFC5JCJZ9701	2018	NA	DP	3343	FL	1/16/2018	1/24/2018
710283	4UZACEFC7JCJY7209	2018	NA	DP	3343	FL	11/30/2017	12/8/2017
710284	4UZACEFC5JCJW3586	2018	NA	DP	3343	FL	10/9/2017	10/17/2017
710285	4UZACEFC5JCJX3650	2018	NA	DP	3341	FL	10/30/2017	11/7/2017
710286	4UZACEFC5JCJW7511	2018	NA	DP	3341	FL	10/13/2017	10/23/2017
710288	4UZACEFC0JCKC6928	2018	NA	DP	3343	FL	2/22/2018	3/2/2018
710289	4UZACEFCXJCKC1025	2018	NA	DP	3341	FL	2/13/2018	2/21/2018
710290	4UZACEFC3JCJY7210	2018	NA	DP	3341	FL	12/1/2017	12/11/2017
710291	4UZACEFC7JCKA3680	2018	NA	DP	3343	FL	1/26/2018	2/5/2018

Prod#	VIN Number	Year	Brand	Type	Floor	Chassis	Date In	Date Off
710292	4UZACEFC7KCKE8412	2018	NA	DP	3343	FL	3/22/2018	4/2/2018
710294	4UZACEFC6KCKD1276	2018	NA	DP	3343	FL	3/2/2018	3/9/2018
710295	4UZACEFC0KCKF4391	2018	NA	DP	3341	FL	3/8/2018	3/15/2018
710296	4UZACEFC1KCKD8006	2018	NA	DP	3343	FL	3/9/2018	3/16/2018
710298	4UZACEFC9JCKC6927	2018	NA	DP	3341	FL	2/21/2018	3/1/2018
710299	4UZACEFCXKCKL1219	2018	NA	DP	3341	FL	5/18/2018	5/29/2018
710300	4UZACEFC7KCKM3313	2018	NA	DP	3343	FL	5/29/2018	6/5/2018
710303	4UZACEFC5JCKA0650	2018	NA	DP	3343	FL	1/22/2018	1/30/2018
710304	4UZACEFC3JCJZ9700	2018	NA	DP	3343	FL	1/16/2018	1/23/2018
710305	4UZACEFC9JCKA3678	2018	NA	DP	3341	FL	1/25/2018	2/1/2018
710306	4UZACEFC8JCJX7059	2018	NA	DP	3343	FL	10/31/2017	11/8/2017
710307	4UZACEFC2JCKA8981	2018	NA	DP	3341	FL	2/2/2018	2/9/2018
710308	4UZACEFC5KCKH4412	2018	NA	DP	3343	FL	4/12/2018	4/20/2018
710309	4UZACEFC7KCKH4413	2018	NA	DP	3343	FL	4/13/2018	4/20/2018
710310	4UZACEFC8JCJZ5559	2018	NA	DP	3343	FL	1/12/2018	1/19/2018
710312	4UZACEFC4JCJX7060	2018	NA	DP	3341	FL	11/6/2017	11/14/2017
710313	4UZACEFC6KCKK2677	2018	NA	DP	3343	FL	5/9/2018	5/17/2018
710314	4UZACEFC3KCKH4411	2018	NA	DP	3341	FL	4/11/2018	4/18/2018
710317	4UZACEFC9JCJZ3500	2018	NA	DP	3343	FL	1/11/2018	1/18/2018
710318	4UZACEFCXJCJY9455	2018	NA	DP	3343	FL	12/12/2017	12/20/2017
710319	4UZACEFC6JCJZ5561	2018	NA	DP	3343	FL	1/9/2018	1/17/2018
710320	4UZACEFC6KCKD5604	2018	NA	DP	3343	FL	3/5/2018	3/12/2018
710321	4UZACEFC0JCKA3679	2018	NA	DP	3343	FL	2/6/2018	2/13/2018
710322	4UZACEFC4JCJZ3498	2018	NA	DP	3341	FL	12/13/2017	12/20/2017
710324	4UZACEFC7JCKA0651	2018	NA	DP	3343	FL	1/24/2018	1/31/2018
710325	4UZACEFC4KCKD1275	2018	NA	DP	3343	FL	2/26/2018	3/5/2018
710326	4UZACEFCXKCKD8005	2018	NA	DP	3341	FL	3/7/2018	3/14/2018
710327	4UZACEFC8KCKD1277	2018	NA	DP	3343	FL	2/28/2018	3/7/2018
710328	4UZACEFC7JCKC6926	2018	NA	DP	3343	FL	2/19/2018	2/27/2018
710329	4UZACEFC8JCKC1024	2018	NA	DP	3341	FL	2/20/2018	2/28/2018
710330	4UZACEFC3JCKB2537	2018	NA	DP	3341	FL	2/12/2018	2/19/2018
710331	4UZACEFC6KCKF4394	2018	NA	DP	3341	FL	4/3/2018	4/10/2018
710332	4UZACEFCXKCKD9168	2018	NA	DP	3343	FL	3/14/2018	3/21/2018
710333	4UZACEFC4JCKA8982	2018	NA	DP	3343	FL	2/5/2018	2/12/2018
710334	4UZACEFC9KCJY2675	2019	NA	DP	3345	FL	12/12/2017	12/20/2017
710335	4UZACEFC8KCKD9167	2018	NA	DP	3343	FL	3/26/2018	4/4/2018
710336	4UZACEFC7KCKE8409	2018	NA	DP	3343	FL	3/15/2018	3/23/2018
710337	4UZACEFC9KCKE8413	2018	NA	DP	3341	FL	3/27/2018	4/5/2018
710338	4UZACEFC3KCKD8007	2018	NA	DP	3341	FL	3/12/2018	3/19/2018
710339	4UZACEFC3KCKE8410	2018	NA	DP	3343	FL	3/19/2018	3/26/2018
710340	4UZACEFC0JCKA8980	2018	NA	DP	3343	FL	2/1/2018	2/8/2018
710342	4UZACEFC9KCKJ5755	2018	NA	DP	3343	FL	4/23/2018	4/30/2018
710343	4UZACEFC0KCJY2676	2019	NA	DP	3343	FL	2/15/2018	2/23/2018
710344	4UZACEFC0KCKJ5756	2018	NA	DP	3343	FL	4/25/2018	5/2/2018
710345	4UZACEFC4KCKK2676	2018	NA	DP	3343	FL	4/24/2018	5/4/2018
710346	4UZACEFC4KCKD5603	2018	NA	DP	3341	FL	3/1/2018	3/8/2018
710347	4UZACEFCXKCKK2679	2018	NA	DP	3343	FL	5/14/2018	5/22/2018
710348	4UZACEFC9KCKH4414	2018	NA	DP	3343	FL	4/16/2018	4/23/2018
710349	4UZACEFC5KCKE8411	2018	NA	DP	3343	FL	3/20/2018	3/27/2018

Prod#	VIN Number	Year	Brand	Type	Floor	Chassis	Date In	Date Off
710350	4UZACEFC3KCKF8631	2018	NA	DP	3343	FL	4/17/2018	4/24/2018
710351	4UZACEFC8KCKK2678	2018	NA	DP	3341	FL	5/1/2018	5/8/2018
710352	4UZACEFC8KCKL1218	2018	NA	DP	3341	FL	5/21/2018	5/30/2018
710353	4UZACEFC6KCKD9166	2018	NA	DP	3343	FL	3/13/2018	3/20/2018
710354	4UZACEFC2KCKF4392	2018	NA	DP	3343	FL	3/21/2018	3/28/2018
710355	4UZACEFC3KCKF8628	2018	NA	DP	3341	FL	4/3/2018	4/11/2018
710356	4UZACEFC5KCKF8629	2018	NA	DP	3343	FL	4/6/2018	4/13/2018
710358	4UZACEFC6KCKL1217	2018	NA	DP	3343	FL	6/1/2018	6/8/2018
710359	4UZACEFC5KCKM3312	2018	NA	DP	3343	FL	5/30/2018	6/6/2018
710360	4UZACEFC1KCKF8630	2018	NA	DP	3341	FL	4/9/2018	4/17/2018
710361	4UZACEFC6KCKH5505	2019	NA	DP	3345	FL	5/4/2018	5/15/2018
710362	4UZACEFC5KCKT1497	2019	NA	DP	3343	FL	7/16/2018	7/23/2018
710363	4UZACEFCXKCKT4282	2019	NA	DP	3345	FL	7/25/2018	8/1/2018
710364	4UZACEFC7KCKT1498	2019	NA	DP	3341	FL	7/17/2018	7/24/2018
710365	4UZACEFC5KCKN3306	2019	NA	DP	3345	FL	6/11/2018	6/19/2018
710366	4UZACEFC2KCKX9054	2019	NA	DP	3345	FL	9/19/2018	9/26/2018
710369	4UZACEFC5KCLC9957	2019	NA	DP	3341	FL	10/16/2018	10/23/2018
710370	4UZACEFC1KCLM7473	2019	NA	DP	3341	FL	1/24/2019	2/5/2019
710371	4UZACEFC2KCKP1004	2019	NA	DP	3341	FL	6/7/2018	6/15/2018
710373	4UZACEFC4KCKL1216	2018	NA	DP	3343	FL	5/17/2018	5/24/2018
710374	4UZACEFC6KCLG5236	2019	NA	DP	3341	FL	10/29/2018	11/5/2018
710376	4UZACEFC2KCLM7479	2019	NA	DP	3343	FL	2/15/2019	2/22/2019
710378	4UZACEFC4KCKX9055	2019	NA	DP	3341	FL	9/20/2018	9/27/2018
710379	4UZACEFC8KCKV2411	2019	NA	DP	3341	FL	9/6/2018	9/12/2018
710381	4UZACEFC8KCKV7382	2019	NA	DP	3341	FL	8/29/2018	9/6/2018
710384	4UZACEFC9KCKP0965	2019	NA	DP	3341	FL	6/12/2018	6/20/2018
710385	4UZACEFC4KCKW8590	2019	NA	DP	3343	FL	8/23/2018	8/31/2018
710386	4UZACEFC3KCLM7474	2019	NA	DP	3345	FL	2/1/2019	2/8/2019
710387	4UZACEFC0KCLM7531	2019	NA	DP	3345	FL	5/8/2019	5/15/2019
710388	4UZACEFCXKCKV7383	2019	NA	DP	3345	FL	8/21/2018	8/29/2018
710389	4UZACEFC1KCLM7506	2019	NA	DP	3343	FL	3/25/2019	4/1/2019
710390	4UZACEFC2KCLM7515	2019	NA	DP	3343	FL	4/23/2019	4/30/2019
710391	4UZACEFC7KCKP0964	2019	NA	DP	3343	FL	5/24/2018	6/4/2018
710392	4UZACEFC2KCLL7308	2019	NA	DP	3343	FL	2/6/2019	2/13/2019
710393	4UZACEFC8KCLG5593	2019	NA	DP	3343	FL	11/19/2018	11/28/2018
710394	4UZACEFC5KCKP8433	2019	NA	DP	3341	FL	6/25/2018	7/11/2018
710395	4UZACEFC7KCKW0631	2019	NA	DP	3343	FL	9/11/2018	9/18/2018
710398	4UZACEFC3KCKS5472	2019	NA	DP	3343	FL	7/12/2018	7/20/2018
710399	4UZACEFC4KCKM9909	2019	NA	DP	3343	FL	8/6/2018	8/14/2018
710403	4UZACEFCXKCKP8430	2019	NA	DP	3343	FL	6/18/2018	6/26/2018
710404	4UZACEFC7KCKX4609	2019	NA	DP	3345	FL	9/13/2018	9/20/2018
710405	4UZACEFCXKCKU4844	2019	NA	DP	3343	FL	8/8/2018	8/16/2018
710406	4UZACEFC9KCKP1002	2019	NA	DP	3345	FL	6/14/2018	6/22/2018
710407	4UZACEFC8KCKT8086	2019	NA	DP	3343	FL	7/25/2018	8/2/2018
710410	4UZACEFC9KCKM3314	2019	NA	DP	3341	FL	8/10/2018	8/20/2018
710419	4UZACEFC7KCLC9958	2019	NA	DP	3345	FL	10/17/2018	10/24/2018
710420	4UZACEFC7KCLM7476	2019	NA	DP	3343	FL	1/14/2019	1/21/2019
710426	4UZACEFC2KCLM7496	2019	NA	DP	3345	FL	4/8/2019	4/15/2019
710427	4UZACEFC9KCLM7527	2019	NA	DP	3345	FL	5/9/2019	5/16/2019

Prod#	VIN Number	Year	Brand	Type	Floor	Chassis	Date In	Date Off
710428	4UZACEFC3KCKY2125	2019	NA	DP	3343	FL	9/24/2018	10/1/2018
710433	4UZACEFC6KCLG5592	2019	NA	DP	3343	FL	11/7/2018	11/14/2018
710434	4UZACEFC8KCLM7504	2019	NA	DP	3345	FL	3/26/2019	4/2/2019
710450	4UZACEFC2KCLG5590	2019	NA	DP	3343	FL	11/12/2018	11/19/2018
710453	4UZACEFC1KCLJ4375	2019	NA	DP	3343	FL	12/19/2018	1/10/2019
710456	4UZACEFC3KCLC9956	2019	NA	DP	3345	FL	10/18/2018	10/25/2018
710457	4UZACEFC5KCLM7492	2019	NA	DP	3343	FL	3/11/2019	3/18/2019
710458	4UZACEFC8KCKX9057	2019	NA	DP	3343	FL	9/21/2018	9/28/2018
710460	4UZACEFC6KCLM7517	2019	NA	DP	3343	FL	4/17/2019	4/25/2019
710461	4UZACEFCXKCLM7472	2019	NA	DP	3343	FL	12/7/2018	12/14/2018
710463	4UZACEFCXKCLJ9526	2019	NA	DP	3343	FL	1/15/2019	1/22/2019
710464	4UZACEFCXKCLM7486	2019	NA	DP	3345	FL	2/18/2019	2/25/2019
710465	4UZACEFC1KCLM7490	2019	NA	DP	3343	FL	2/28/2019	3/7/2019
710466	4UZACEFC4KCLM7502	2019	NA	DP	3345	FL	3/19/2019	3/27/2019
710467	4UZACEFC9KCLM7480	2019	NA	DP	3343	FL	4/3/2019	4/10/2019
710475	4UZACEFC3KCLG8272	2019	NA	DP	3345	FL	11/28/2018	12/5/2018
710478	4UZACEFC4KCLM7516	2019	NA	DP	3343	FL	4/4/2019	4/11/2019
710479	4UZACEFCXKCLM7522	2019	NA	DP	3343	FL	4/24/2019	5/1/2019
710481	4UZACEFC6KCKU4842	2019	NA	DP	3345	FL	8/1/2018	8/8/2018
710484	4UZACEFC1KCKP8431	2019	NA	DP	3343	FL	6/20/2018	6/28/2018
710485	4UZACEFC6KCKX9056	2019	NA	DP	3345	FL	10/4/2018	10/11/2018
710486	4UZACEFC7KCKP8434	2019	NA	DP	3345	FL	6/26/2018	7/12/2018
710487	4UZACEFC1KCKV7384	2019	NA	DP	3343	FL	8/31/2018	9/10/2018
710495	4UZACEFC1KCKS5471	2019	NA	DP	3343	FL	6/27/2018	7/13/2018
710496	4UZACEFC5KCLM7525	2019	NA	DP	3345	FL	5/2/2019	5/9/2019
710502	4UZACEFC3KCLM7488	2019	NA	DP	3341	FL	2/26/2019	3/5/2019
710504	4UZACEFC7KCKX4612	2019	NA	DP	3345	FL	9/14/2018	9/21/2018
710505	4UZACEFC8KCKY4646	2019	NA	DP	3343	FL	10/12/2018	10/19/2018
710506	4UZACEFC3KCKT1496	2019	NA	DP	3343	FL	7/11/2018	7/19/2018
710507	4UZACEFC7KCLM2701	2019	NA	DP	3345	FL	1/16/2019	1/23/2019
710508	4UZACEFC1KCKT8088	2019	NA	DP	3343	FL	8/2/2018	8/10/2018
710510	4UZACEFC5KCKY2126	2019	NA	DP	3343	FL	9/26/2018	10/3/2018
710511	4UZACEFC3KCLE9947	2019	NA	DP	3343	FL	10/22/2018	10/29/2018
710512	4UZACEFC1KCLC9955	2019	NA	DP	3343	FL	10/19/2018	10/26/2018
710513	4UZACEFC7KCLE9949	2019	NA	DP	3341	FL	10/24/2018	10/31/2018
710514	4UZACEFC4KCLG5235	2019	NA	DP	3341	FL	10/25/2018	11/16/2018
710515	4UZACEFC8KCLG5237	2019	NA	DP	3341	FL	10/30/2018	11/6/2018
710516	4UZACEFC5KCLL3558	2019	NA	DP	3345	FL	12/20/2018	1/11/2019
710517	4UZACEFC6KCLM7520	2019	NA	DP	3343	FL	4/25/2019	5/2/2019
710518	4UZACEFC4KCLM7533	2019	NA	DP	3341	FL	5/14/2019	5/22/2019
710519	4UZACEFCXKCLG5238	2019	NA	DP	3345	FL	11/1/2018	11/8/2018
710520	4UZACEFC1KCLH6614	2019	NA	DP	3341	FL	11/28/2018	12/5/2018
710521	4UZACEFC8KCKW8589	2019	NA	DP	3343	FL	9/10/2018	9/14/2018
710522	4UZACEFC3KCKP8432	2019	NA	DP	3343	FL	6/21/2018	7/9/2018
710523	4UZACEFCXKCKV2412	2019	NA	DP	3345	FL	8/30/2018	9/7/2018
710525	4UZACEFC8KCLM7518	2019	NA	DP	3345	FL	4/18/2019	4/29/2019
710529	4UZACEFC9KCLM7494	2019	NA	DP	3345	FL	3/8/2019	3/15/2019
710530	4UZACEFCXKCLH6613	2019	NA	DP	3343	FL	11/29/2018	12/6/2018
710531	4UZACEFC5KCKS5473	2019	NA	DP	3343	FL	7/9/2018	7/17/2018

Prod#	VIN Number	Year	Brand	Type	Floor	Chassis	Date In	Date Off
710532	4UZACEFC2KCLM7482	2019	NA	DP	3343	FL	1/28/2019	2/6/2019
710534	4UZACEFCXKCLM7505	2019	NA	DP	3343	FL	3/21/2019	3/28/2019
710535	4UZACEFC9KCLJ1076	2019	NA	DP	3343	FL	12/6/2018	12/13/2018
710536	4UZACEFC3KCLJ9528	2019	NA	DP	3343	FL	1/11/2019	1/18/2019
710539	4UZACEFC4KCLL7309	2019	NA	DP	3345	FL	1/18/2019	1/25/2019
710542	4UZACEFC4KCLG5591	2019	NA	DP	3343	FL	11/14/2018	11/21/2018
710543	4UZACEFC4KCLG5588	2019	NA	DP	3343	FL	11/8/2018	11/15/2018
710545	4UZACEFC2KCLJ1078	2019	NA	DP	3343	FL	12/12/2018	12/20/2018
710546	4UZACEFC1KCLG5239	2019	NA	DP	3343	FL	11/15/2018	11/26/2018
710550	4UZACEFC1KCKU9219	2019	NA	DP	3345	FL	8/17/2018	8/24/2018
710551	4UZACEFC3KCLH6615	2019	NA	DP	3341	FL	11/30/2018	12/7/2018
710552	4UZACEFC3KCLM7507	2019	NA	DP	3345	FL	3/22/2019	3/29/2019
710553	4UZACEFC0KCKY4642	2019	NA	DP	3341	FL	10/5/2018	10/12/2018
710557	4UZACEFC6KCKT4280	2019	NA	DP	3345	FL	7/19/2018	7/27/2018
710558	4UZACEFC5KCLE9948	2019	NA	DP	3343	FL	10/26/2018	11/2/2018
710560	4UZACEFC5KCKX4608	2019	NA	DP	3341	FL	9/27/2018	10/4/2018
710562	4UZACEFC7KCLM7512	2019	NA	DP	3345	FL	4/9/2019	4/16/2019
710563	4UZACEFC5KCLG8273	2019	NA	DP	3343	FL	12/13/2018	1/7/2019
710564	4UZACEFC3KCLM7491	2019	NA	DP	3343	FL	3/1/2019	3/8/2019
710565	4UZACEFC5KCKW0630	2019	NA	DP	3343	FL	9/4/2018	9/11/2018
710566	4UZACEFC0KCKP1003	2019	NA	DP	3343	FL	6/6/2018	6/13/2018
710567	4UZACEFC4KCKN3300	2019	NA	DP	3341	FL	8/3/2018	8/13/2018
710568	4UZACEFC8KCKT4281	2019	NA	DP	3343	FL	7/23/2018	7/30/2018
710569	4UZACEFC8KCKU4843	2019	NA	DP	3345	FL	8/7/2018	8/15/2018
710570	4UZACEFC5KCKX4611	2019	NA	DP	3341	FL	10/1/2018	10/8/2018
710571	4UZACEFCXKCKU9221	2019	NA	DP	3341	FL	8/21/2018	8/29/2018
710572	4UZACEFC6KCKV2410	2019	NA	DP	3345	FL	8/17/2018	8/28/2018
710573	4UZACEFC7KCKY2127	2019	NA	DP	3343	FL	10/2/2018	10/9/2018
710574	4UZACEFC6KCKY4645	2019	NA	DP	3343	FL	10/8/2018	10/15/2018
710575	4UZACEFC8KCKU9220	2019	NA	DP	3343	FL	8/15/2018	8/22/2018
710576	4UZACEFC3KCKX4610	2019	NA	DP	3343	FL	9/17/2018	9/24/2018
710577	4UZACEFC9KCKY2128	2019	NA	DP	3341	FL	10/3/2018	10/10/2018
710578	4UZACEFC6KCLM7484	2019	NA	DP	3345	FL	2/20/2019	2/27/2019
710579	4UZACEFC6KCLG5589	2019	NA	DP	3343	FL	11/2/2018	11/9/2018
710580	4UZACEFC4KCKY4644	2019	NA	DP	3345	FL	10/10/2018	10/17/2018
710581	4UZACEFC2KCKY4643	2019	NA	DP	3343	FL	10/9/2018	10/16/2018
710583	4UZACEFC7KCLL3559	2019	NA	DP	3345	FL	1/8/2019	1/15/2019
710584	4UZACEFC7KCLM7493	2019	NA	DP	3343	FL	3/5/2019	3/12/2019
710585	4UZACEFCXKCLJ4374	2019	NA	DP	3343	FL	12/10/2018	12/18/2018
710586	4UZACEFC5KCLM2700	2019	NA	DP	3343	FL	1/9/2019	1/16/2019
710587	4UZACEFC1KCLG8271	2019	NA	DP	3343	FL	11/21/2018	11/30/2018
710588	4UZACEFC8KCLJ4373	2019	NA	DP	3343	FL	12/5/2018	12/12/2018
710589	4UZACEFCXKCLG8270	2019	NA	DP	3343	FL	11/5/2018	11/12/2018
710590	4UZACEFC5KCLH6616	2019	NA	DP	3345	FL	12/17/2018	1/8/2019
710591	4UZACEFC0KCLL7307	2019	NA	DP	3343	FL	1/10/2019	1/17/2019
710593	4UZACEFCXKCLM7519	2019	NA	DP	3343	FL	4/15/2019	4/23/2019
710594	4UZACEFC0KCLJ1077	2019	NA	DP	3341	FL	12/3/2018	12/10/2018
710595	4UZACEFC9KCLM2702	2019	NA	DP	3343	FL	1/21/2019	1/28/2019
710596	4UZACEFC0KCLM2703	2019	NA	DP	3343	FL	1/22/2019	1/29/2019

Prod#	VIN Number	Year	Brand	Type	Floor	Chassis	Date In	Date Off
710597	4UZACEFC5KCLJ9529	2019	NA	DP	3345	FL	1/7/2019	1/14/2019
710598	4UZACEFC4KCLM7497	2019	NA	DP	3343	FL	3/7/2019	3/14/2019
710599	4UZACEFC8KCLM7485	2019	NA	DP	3343	FL	3/4/2019	3/11/2019
710600	4UZACEFC1KCLJ9527	2019	NA	DP	3343	FL	12/11/2018	12/19/2018
710601	4UZACEFC1KCLM7487	2019	NA	DP	3343	FL	2/21/2019	2/28/2019
710602	4UZACEFC5KCLM7475	2019	NA	DP	3343	FL	1/29/2019	2/7/2019
710603	4UZACEFC3KCLM7510	2019	NA	DP	3343	FL	4/1/2019	4/8/2019
710604	4UZACEFC8KCLM7471	2019	NA	DP	3343	FL	1/23/2019	2/1/2019
710605	4UZACEFC0KCLM7481	2019	NA	DP	3343	FL	2/12/2019	2/19/2019
710607	4UZACEFC5KCLM7489	2019	NA	DP	3343	FL	2/22/2019	3/1/2019
710611	4UZACEFC2KCLM7529	2019	NA	DP	3343	FL	5/10/2019	5/17/2019
710612	4UZACEFC6KCLM7534	2019	NA	DP	3343	FL	5/16/2019	5/24/2019
710614	4UZACEFC6KCLM7498	2019	NA	DP	3343	FL	4/16/2019	4/24/2019
710615	4UZACEFC4KCLM7483	2019	NA	DP	3343	FL	2/27/2019	3/6/2019
710616	4UZACEFC9KCLM7477	2019	NA	DP	3343	FL	2/13/2019	2/20/2019
710618	4UZACEFC9KCLM7513	2019	NA	DP	3341	FL	4/10/2019	4/17/2019
710619	4UZACEFC8KCLM7499	2019	NA	DP	3343	FL	3/13/2019	3/20/2019
710620	4UZACEFC0KCLM7500	2019	NA	DP	3345	FL	3/15/2019	3/22/2019
710621	4UZACEFC0KCLM7495	2019	NA	DP	3345	FL	3/14/2019	3/21/2019
710622	4UZACEFC6KCLM7503	2019	NA	DP	3343	FL	3/27/2019	4/3/2019
710623	4UZACEFC2KCLM7501	2019	NA	DP	3345	FL	3/18/2019	3/25/2019
710624	4UZACEFC5KCLM7508	2019	NA	DP	3343	FL	3/28/2019	4/4/2019
710625	4UZACEFC3KCLM7524	2019	NA	DP	3343	FL	4/29/2019	5/7/2019
710627	4UZACEFC5KCLM7511	2019	NA	DP	3343	FL	4/2/2019	4/9/2019
710628	4UZACEFC0KCLM7514	2019	NA	DP	3345	FL	4/11/2019	4/22/2019
710629	4UZACEFC0KCLM7528	2019	NA	DP	3343	FL	5/6/2019	5/13/2019
710630	4UZACEFC8KCLM7521	2019	NA	DP	3343	FL	4/26/2019	5/3/2019
710631	4UZACEFC6KCLW3944	2019	NA	DP	3341	FL	5/17/2019	5/28/2019
710632	4UZACEFC1KCLM7523	2019	NA	DP	3343	FL	5/1/2019	5/8/2019
710634	4UZACEFC7KCLM7526	2019	NA	DP	3341	FL	5/3/2019	5/10/2019
710635	4UZACEFC9KCLM7530	2019	NA	DP	3343	FL	5/7/2019	5/14/2019
710636	4UZACEFC2KCLM7532	2019	NA	DP	3343	FL	5/13/2019	5/20/2019
801238	4UZFTFG2JCJD9867	2018	EX	DP	4536	FL	2/6/2017	2/13/2017
801248	4UZFTFG7JCJR6604	2018	EX	DP	4553	FL	5/19/2017	6/1/2017
801253	4UZFTFG7JCJR3945	2018	EX	DP	4531	FL	6/15/2017	6/23/2017
801256	4UZFTFG3JCJS6792	2018	EX	DP	4531	FL	6/28/2017	7/14/2017
801261	4UZFTFG5JCJT8412	2018	EX	DP	4531	FL	8/10/2017	8/18/2017
801262	4UZFTFG0JCJX3648	2018	EX	DP	4531	FL	10/18/2017	10/26/2017
801266	4UZFTFG0JCJT1853	2018	EX	DP	4553	FL	8/2/2017	8/10/2017
801268	4UZFTFG3JCJU2250	2018	EX	DP	4531	FL	8/22/2017	8/30/2017
801273	4UZFTFG0JCJU5039	2018	EX	DP	4534	FL	9/13/2017	9/20/2017
801276	4UZFTFG4JCJX9212	2018	EX	DP	4531	FL	11/10/2017	11/20/2017
801277	4UZFTFGXJCJX7058	2018	EX	DP	4533	FL	10/26/2017	11/3/2017
801292	4UZFTFG6JCJY4069	2018	EX	DP	4533	FL	2/9/2018	2/16/2018
801297	4UZFTFG7JCKA9346	2018	EX	DP	4531	FL	2/19/2018	2/26/2018
801299	4UZFTFG6KCJY2517	2019	EX	DP	4543	FL	2/12/2018	2/19/2018
801300	4UZFTFG9JCKA9347	2018	EX	DP	4531	FL	4/9/2018	4/16/2018
801304	4UZFTFG9KCKH5494	2019	EX	DP	4551	FL	5/3/2018	5/14/2018
801305	4UZFTFG6KCKD1274	2018	EX	DP	4531	FL	5/7/2018	5/16/2018

Prod#	VIN Number	Year	Brand	Type	Floor	Chassis	Date In	Date Off
801310	4UZFG0KCKP1001	2019	EX	DP	4579	FL	5/29/2018	6/6/2018
801311	4UZFG7KCKP8429	2019	EX	DP	4543	FL	7/13/2018	7/23/2018
801314	4UZFGXKCKV2407	2019	EX	DP	4551	FL	10/8/2018	10/15/2018
801315	4UZFG3KCKV2409	2019	EX	DP	4579	FL	10/16/2018	10/23/2018
801316	4UZFG1KCKV2408	2019	EX	DP	4543	FL	10/12/2018	10/19/2018
801323	4UZFG0KCLM7445	2019	EX	DP	4551	FL	3/25/2019	4/1/2019
801327	4UZFG1KCLH6612	2019	EX	DP	4551	FL	11/21/2018	11/30/2018
801328	4UZFG3KCKS5470	2019	EX	DP	4543	FL	8/13/2018	8/20/2018
801339	4UZFGXKCKU9216	2019	EX	DP	4551	FL	9/11/2018	9/18/2018
801344	4UZFGXKCLG5222	2019	EX	DP	4533	FL	10/24/2018	10/31/2018
801347	4UZFG6KCLG5587	2019	EX	DP	4551	FL	11/15/2018	11/27/2018
801355	4UZFGXKCLJ4372	2019	EX	DP	4543	FL	2/20/2019	2/27/2019
801357	4UZFG5KCLL3556	2019	EX	DP	4551	FL	2/27/2019	3/7/2019
801358	4UZFG2KCLM7446	2019	EX	DP	4543	FL	4/1/2019	4/9/2019
801359	4UZFG7KCLL3557	2019	EX	DP	4551	FL	4/17/2019	4/25/2019
801360	4UZFG3KCLJ1104	2019	EX	DP	4551	FL	4/30/2019	5/7/2019
801361	4UZFG4KCLM7447	2019	EX	DP	4543	FL	5/14/2019	5/21/2019
904652	4UZFBG6KCKK3685	2019	MA	DP	4579	FL	5/23/2018	6/1/2018
904654	4UZFBG9KCLJ4367	2019	MA	DP	4551	FL	12/6/2018	12/13/2018
904655	4UZFBG8KCKT1495	2019	MA	DP	4579	FL	8/1/2018	8/8/2018
904657	4UZFBG0KCKW8587	2019	MA	DP	4579	FL	8/28/2018	9/5/2018
904658	4UZFBG3KCKW0628	2019	MA	DP	4534	FL	8/24/2018	9/4/2018
904661	4UZFBG1KCKW0627	2019	MA	DP	4551	FL	8/14/2018	8/22/2018
904667	4UZFBG7KCKR5270	2019	MA	DP	4551	FL	7/24/2018	7/31/2018
904669	4UZFBG6KCLE9945	2019	MA	DP	4579	FL	10/15/2018	10/22/2018
904674	4UZFBG2KCLM2754	2019	MA	DP	4551	FL	3/12/2019	3/19/2019
904676	4UZFBG6KCKP8427	2019	MA	DP	4551	FL	7/25/2018	8/2/2018
904680	4UZFBG0KCLJ4368	2019	MA	DP	4551	FL	12/12/2018	12/20/2018
904689	4UZFBG3KCKN3307	2019	MA	DP	4543	FL	7/11/2018	7/19/2018
904693	4UZFBG4KCKN3302	2019	MA	DP	4550	FL	6/21/2018	7/9/2018
904698	4UZFBG3KCKY4640	2019	MA	DP	4535	FL	9/25/2018	10/2/2018
904712	4UZFBG4KCLM2755	2019	MA	DP	4543	FL	2/25/2019	3/4/2019
904720	4UZFBG0KCKU9215	2019	MA	DP	4543	FL	8/2/2018	8/9/2018
904724	4UZFBG4KCKT4278	2019	MA	DP	4543	FL	7/31/2018	8/8/2018
904726	4UZFBG9KCKW8586	2019	MA	DP	4551	FL	8/30/2018	9/7/2018
904727	4UZFBG3KCKV7325	2019	MA	DP	4551	FL	8/14/2018	8/21/2018
904732	4UZFBG0KCLG5221	2019	MA	DP	4543	FL	10/23/2018	10/30/2018
904734	4UZFBG5KCKY4641	2019	MA	DP	4534	FL	10/4/2018	10/11/2018
904735	4UZFBG0KCLH6610	2019	MA	DP	4543	FL	11/5/2018	11/12/2018
904737	4UZFBG9KCLG5573	2019	MA	DP	4551	FL	10/24/2018	10/31/2018
904739	4UZFBG6KCLL3555	2019	MA	DP	4551	FL	12/3/2018	12/10/2018
904741	4UZFBG9KCLJ4370	2019	MA	DP	4551	FL	2/4/2019	2/11/2019
904743	4UZFBG2KCLJ4369	2019	MA	DP	4551	FL	12/20/2018	1/11/2019
904751	4UZFBG6KCLM2756	2019	MA	DP	4533	FL	3/14/2019	3/22/2019
904758	4UZFTFM7KCLV4057	2019	MA	DP	4551	FL	5/7/2019	5/14/2019
904760	4UZFBG8KCLM2757	2019	MA	DP	4543	FL	4/4/2019	4/11/2019
904761	4UZFTFM8KCKY3242	2019	MA	DP	4551	FL	4/18/2019	4/26/2019

Prod#	VIN Number	Year	Brand	Type	Floor	Chassis	Date In	Date Off
Canadian Units								
501598	4UZFG9KCKX9050	2019	LA	DP	4576	FL	9/10/2018	9/17/2018
501630	4UZFG2KCKX9052	2019	LA	DP	4551	FL	10/2/2018	10/9/2018
501635	4UZFG3KCKT4279	2019	LA	DP	4534	FL	6/19/2018	6/27/2018
607456	4UZCHF5KCLH6608	2019	DS	DP	4369	FL	10/10/2018	10/17/2018
607500	4UZACHFE7KCKT8079	2019	DS	DP	3736	FL	7/25/2018	8/1/2018
607501	4UZACHFE5KCLM7284	2019	DS	DP	3736	FL	2/7/2019	2/14/2019
607502	4UZCHF2KCLM7331	2019	DS	DP	4018	FL	4/9/2019	4/16/2019
607503	4UZCHF2KCLM7345	2019	DS	DP	4018	FL	5/13/2019	5/21/2019
607504	4UZCHF4KCLL7304	2019	DS	DP	4328	FL	2/7/2019	2/14/2019
607505	4UZCHF8KCKT8081	2019	DS	DP	4018	FL	7/13/2018	7/20/2018
607506	4UZCHF6KCKW8583	2019	DS	DP	4310	FL	8/24/2018	9/4/2018
607541	4UZCHFEXKCKV2399	2019	DS	DP	4369	FL	8/14/2018	8/22/2018
607729	4UZCHF1KCLM7367	2019	DS	DP	4363	FL	3/20/2019	3/27/2019
607856	4UZACHFE6KCKU4830	2019	DS	DP	3736	FL	7/27/2018	8/3/2018
607857	4UZCHF4KCLM7329	2019	DS	DP	4018	FL	4/11/2019	4/18/2019
608003	4UZACHFE6KCKV7321	2019	DS	DP	3736	FL	8/15/2018	8/23/2018
608004	4UZACHFE6KCLV0341	2019	DS	DP	3736	FL	4/18/2019	4/29/2019
608043	4UZACHFE5KCLG5571	2019	DS	DP	3717	FL	10/16/2018	10/23/2018
608240	4UZACHFE3KCLM7283	2019	DS	DP	3717	FL	1/23/2019	2/1/2019
608308	4UZACHFE3KCLM7297	2019	DS	DP	3736	FL	4/2/2019	4/9/2019
608311	4UZCHF2KCLM7328	2019	DS	DP	4018	FL	3/22/2019	4/1/2019
608367	4UZCHF2KCLW2346	2019	DS	DP	4369	FL	5/17/2019	5/28/2019
710212	4UZACEFC3JCU2252	2018	NA	DP	3341	FL	8/29/2017	9/6/2017
710213	4UZACEFC9JCS8467	2018	NA	DP	3343	FL	8/1/2017	8/9/2017
710217	4UZACEFC9JCJW0707	2018	NA	DP	3343	FL	9/29/2017	10/9/2017
710218	4UZACEFC1JCJR6374	2018	NA	DP	3343	FL	6/27/2017	7/13/2017
710237	4UZACEFC4JCU9968	2018	NA	DP	3343	FL	9/13/2017	9/21/2017
710238	4UZACEFC0JCJV3676	2018	NA	DP	3341	FL	9/19/2017	9/27/2017
710241	4UZACEFC0JCJT5534	2018	NA	DP	3343	FL	8/17/2017	8/25/2017
710242	4UZACEFC7JCJX3651	2018	NA	DP	3341	FL	10/23/2017	10/31/2017
710323	4UZACEFC4KCKF4393	2018	NA	DP	3343	FL	3/23/2018	4/3/2018
710377	4UZACEFC3KCKN3305	2019	NA	DP	3343	FL	6/4/2018	6/11/2018
710400	4UZACEFC6KCKW8591	2019	NA	DP	3341	FL	9/12/2018	9/19/2018
710435	4UZACEFCXKCKT8087	2019	NA	DP	3343	FL	7/30/2018	8/7/2018
710438	4UZACEFC9KCKW0632	2019	NA	DP	3343	FL	9/7/2018	9/13/2018
710439	4UZACEFC0KCLM7478	2019	NA	DP	3345	FL	2/7/2019	2/14/2019
710626	4UZACEFC7KCLM7509	2019	NA	DP	3341	FL	3/29/2019	4/5/2019
904662	4UZFBG2KCKW8588	2019	MA	DP	4534	FL	9/17/2018	9/24/2018