

Product Notice

Date: February 24th, 2021

Contact Number: 734-384-7898

Contact Name(s): Tenneco / DRiV Warranty



Products

Part Number(s): K750125 and K750126

Product Name: Quick Steer Stabilizer Bar Links

Packaging Label Date Codes Affected: All

Reason / Process For Return



A manufacturing error has been identified related to the part numbers listed above. Affected parts cannot be installed. This is not a safety issue.

1. Please scrap the parts.
2. Email warranty@driv.com with the number of units scrapped, reference TRC #25643 in the subject line.
3. Credit will be issued to your account.
4. Reorder replacement product, as required.

If you have any questions, please call 734-384-7898 and speak with a Warranty CSR.

Visual Aid

Label Example



Part images

