

Bulletin #: C32-0321-0625		<input type="checkbox"/> Take Note	<input checked="" type="checkbox"/> Take Action
<input type="checkbox"/> Retail Operator	<input type="checkbox"/> Sales Pre-Owned	<input type="checkbox"/> Business Manager	<input checked="" type="checkbox"/> Parts & Accessories
<input type="checkbox"/> General Manager	<input type="checkbox"/> Sales New Car	<input type="checkbox"/> Service	<input type="checkbox"/> Administration
Name: Kenny Inoa		Phone Number: 201-571-5623	
Title: Parts Consultant Group Process Lead		Source: Parts Logistics	
Date: March 25, 2021		Supersedes:	



BMW PARTS BULLETIN

TEC313 OIL PIPE RETURN

TAKE ACTION

BMW AG has requested the inspection and return of the following part number:

11 42 7 800 611

Stock should not be sold or installed on any vehicle.

Concerned are all parts delivered and shipped so far designed incorrectly. Please see image below to identify correct part.

Please return all affected part(s) to your facing Regional Distribution Center (RDC). Submit for return using a YR26 damage claim with order reason BM2. A valid BMW delivery and delivery item number must be entered, and TEC313 must appear in the text of your TEC claim.

TEC313 is valid from March 25, 2021, through April 8, 2021. The deadline for filing a claim under TEC313 is April 8, 2021. All parts must be returned to your facing RDC no later than April 22, 2021.

Please reorder the same part number if needed.



