

**FT5068 Hydraulic Tank Rubber Mount Bushing Failures NYCT**

**Technical writer name**  
Devanand

**Manual section** 09

First Level Parts (100% of 251 vehicles)		
Material	Part Number	QTY
Rubber Mount SCB-20I CR-60	N101202	4

**Nb hours Level 1** 1 hr **MQR** 7621-1911

Disposal of parts		
Removed parts are:		When the retained check box is checked, the parts must be retained and returned in accordance with the usual warranty procedure to be reimbursed,
Discarded	Retained	
x	-	

Client	Order	Road numbers		VIN		QTY	Lang.	Customer	Target market	Plant	Config moteur	Model	NR	R1
New York City Transit - New York	LA73	8504	8507	L82J8J9776445	L82J8J9776476	4	E	NYCT	US	PLB	TD	40	x	
New York City Transit - New York	LA76	8508	8633	L82J9J9776924	L82J8K9777144	125	E	NYCT	US	PLB	TD	40	x	
New York City Transit - New York	LB78	8526	8526	L82J3K9776984	L82J3K9776984	1	E	NYCT	US	PLB	TD	40	x	
New York City Transit - New York	LC32	8634	8754	L82JXK9777145	L82J5K9777277	121	E	NYCT	US	PLB	TD	40	x	