

Service and Parts Business

# **Technical Journal**

	TITLE:					
Electrical motor sound information						
REF NO: TJ 36106.1.0	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada				
3 US 7	PARTNER: 7510 Volvo Car USA	ISSUE DATE: 2022-03-14	STATUS DATE: 2022-03-22			
FUNC GROUP: 2103	FUNC DESC: COMPRESSION TEST	Page	1 of 2			

# "Right first time in Time"

#### Attachment

File Name	File Size
TJ 36106 Sound sample ERAD1.wav	6.9368 MB
TJ 36106 Sound sample ERAD2.wav	2.3109 MB
TJ 36106 Sound sample ERAD3.wav	2.9993 MB

#### **DESCRIPTION:**

If there are complaints concerning sounds generated from the ERAD (Electrical Rear Axle Drive) of the vehicle, please follow instruction under "Service".

#### **CSC** Customer Symptom Codes

Code	Description				
8N	Driving/Unusual noise/Unsure when/at all times				
F2	Driving/Unusual noise/During acceleration				
ZE	Idling/Unusual noise				
D2	Front/rear axle/Unusual noise				

## **DTC** Diagnostic Trouble Codes

#### **Vehicle Type**

]	Гуре	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
5	536	ED	E400V6					2021-9999		0000001-99999999	202037-999952

Produced and printed in the USA and available as an electronic document. © 2022 VOLVO CAR USA, LLC

# **Technical Journal 36106.1.0**

#### **SERVICE:**

A whining sound noticeable during electric drive is to be considered as normal.

The attached files (TJ 36106 Sound sample ERAD 1,2 and 3) are examples of normal ERAD sounds under various driving conditions.

For clarity, it is recommended to listen to these files with headphones.

If, after listening to the attached sound sample files, you cannot conclude whether the vehicle in question sounds "normal" or not, please submit a Vehicle Report.

Be sure to record the ERAD sound with a mobile device from the front seat, at head height, and showing the dashboard in which speed and drive mode you are driving.

#### Warranty claim info:

No warranty claim is accepted for a job described in this Technical Journal since it is to be used as a guidance.

## **VEHICLE REPORT:**

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 2103.

# This Technical Journal has three sound files.