## **GPOP - Issue Review System**

Part Number: 68141376A\$, 68156982A\$, 68308727A\$, 68127833A\$

Part Description: A/C Pressure Transducer

**Issue** A/C inoperative and diagnosis leads to pressure transducer. Call Steve Rice at cell **Description:** (248) 867-0061 before replacing the pressure transducer. If no response in 15

minutes, please proceed with repair.

Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquires. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.