

6/15/2016

MY2008 – 2014

RT

GPOP - Issue Review System

Part Number: R4880213A\$, R4880214A\$

Part Description: Shaft - Axle Half

Issue Description: Note: The joint between the splines on the halfshaft and the hub and bearing is an interference fit. The halfshaft nut is to be used to draw the hub and bearing onto the halfshaft splines. This is particularly true if hub and bearing is also being replaced.~

~

~

Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
