Mazda North American Operations Irvine, CA 92618-2922



REFERENCE NO: RF-22-01R3 DATE: 01/12/23

SUBJECT: Gen 6 Infotainment Center Display Repair Kit

This Parts Flash replaces RF-22-01R2 released January 04, 2022. It includes new display repair kit part numbers for the 2018-2019 Mazda2, 2018-2020 CX-3 and 2018-2020 MX-5.

Repair kits are available to replace just the screen. There is no need to replace the entire infotainment display unit as the supply chain has been heavily impacted due to the <u>global shortage of semiconductors</u>.

<u>Please use the table below when ordering the screen repair kits</u>. This can also be found in Service Alert SA-001/23.

Year	Model	Part Number	Description	Qty	Note 1	Note 2	Note 3
2014-2016	Mazda3	BHY1-61-1JZ	Display Repair Kit	1		Includes a center display lens and antistatic rubber gloves	
2017-2018	Mazda3	B6YA-61 1JZ	Display Repair Kit	1	For vehicles equipped with display B61A- 61-1J0*		
2016	Mazda6	GRY7-61-1JZ	Display Repair Kit	1	Applies only to vehicles with P/N GRT7-61-1J0/ A Vehicles with center display P/N GML8-611J0 do not apply		Refer to MGSS for installation instructions
2017-2021	Mazda6	GRY7-61-1JZ	Display Repair Kit	1			
2017-2020	CX-5	K1Y3-61-1JZ	Display Repair Kit	1	Applies only to vehicles with Center Display P/N K123-61-130/ A. Vehicles with center display P/N K123-61-1J0B or later are already modified and do not apply		
2016-2017	Mazda2	D0YP-61-1JZ	Display Repair Kit	1	With display D09H-61-1J0B or older With display		
2018-2019	CX-3						
	Mazda2	D1YP-61-1JZ	Display Repair	1	D23N-61-1J0A or		
2018-2020	CX-3 Mazda2	D2YN-61-1JZA	Kit Display Repair Kit	1	older With display D23N-61-1J0B		-
2019-2022	CX-3						
2016-2017		D0YP-61-1JZ	Display Repair Kit	1	With display NA1P-61-1J0B or older		
2018-2020	MX-5	D1YP-61-1JZ	Display Repair Kit	1	With display ND1F-61-1J0A or older		
2020-2022		D2YN-61-1JZA	Display Repair Kit	1	With display ND1F-61-1J0B/C		