Vehicle Compliance & Analysis

TO: Mercedes-Benz Dealer Principals, General Managers,	FROM: Gregory Gunther, Senior Manager, Vehicle	
Sales Managers, Service Managers, Parts Managers	Compliance and Analysis, Engineering Services	
RE: Service Campaign Launch Notification		
Place Trickle Charger in Trunk	DATE: October 20, 2023	
MY22 SL (232 platform)		

IMPORTANT SERVICE CAMPAIGN LAUNCH

Please note that all customer inquiries should be directed to the Customer Assistance Center at 1-800-FOR-MERCEDES (1-800-367-6372).

Sincerely,

Gregory Gunther

Senior Manager, Vehicle Compliance & Analysis

Mercedes-Benz USA, LLC A Mercedes-Benz Group AG Company



Vehicle Compliance & Analysis

Campaign No. :	Campaign Desc. :				
2023050003	23P5490205	Place Trickle Charger in Trunk			
This is to notify you of th	e Service Campaign Launch	to place a trickle charger in the trunk in <u>3,582</u> Model Year ("MY") 2022 SL be visible and flagged in VMI as "OPEN" on October 20, 2023.			
(p	·	Background			
lssue	determ operati the foll Vehicle	des-Benz AG ("MBAG"), the manufacturer of Mercedes-Benz vehicles, ha ined that on certain MY 2022 SL (232 platform) vehicles, after a longer non onal time of greater than 42 days or with a battery charge of less than 45% owing battery fault message might display in the instrument cluster: "Stop e See Operator's Manual, Switch on vehicle to charge the 12V battery", o rehicle To charge the 12 V battery do not switch off vehicle."			
What We're Doing		A will conduct a service campaign. As a customer convenience measure, an zed Mercedes-Benz dealer will place a trickle charger in the vehicle's trunk.			
Parts	The rei	medy is available and can be performed as necessary.			
	N	/ehicles Affected			
Vehicle Model Year(s)		2022			
Vehicle Model	SL				
	Ve	ehicle Populations			
Total Campaign Populati	ion 3,582				
Next Steps/Notes					
AOMS/SOMS	AOMs -	- This campaign may generate questions from your dealers.			

While we regret any inconvenience this may cause, MBUSA is determined to maintain a high level of vehicle quality and customer satisfaction. Please refer all customer inquiries to the Customer Assistance Center at 1-800-FOR-MERCEDES.

Mercedes-Benz USA, LLC A Mercedes-Benz Group AG Company



Service Campaign Bulletin



Campaign No. 2023050003, October 2023

TO: ALL MERCEDES-BENZ CENTERS

SUBJECT: Model SL (232 platform) Model Year 2022

Place Trickle Charger in Trunk

Mercedes-Benz AG ("MBAG"), the manufacturer of Mercedes-Benz vehicles, has determined that on certain MY 2022 SL (232 platform) vehicles, after a longer non-operational time of greater than 42 days or with a battery charge of less than 45%, the following battery fault message might display in the instrument cluster: "Stop Vehicle See Operator's Manual, Switch on vehicle to charge the 12V battery", or "Stop vehicle To charge the12 V battery do not switch off vehicle." As a customer convenience measure, an authorized Mercedes-Benz dealer will place a trickle charger in the vehicle's trunk.

Prior to performing this Campaign:

- VMI must be checked before performing campaigns to verify that the campaign is required on a specific vehicle. Always check for any other open campaigns, and perform accordingly.
- Please review the entire Campaign bulletin and follow the repair procedure exactly as described.

Approximately 3,582 vehicles are affected.

Order No. P-SC-2023050003

Service Campaign Bulletin

Service Campaign Bulletin

Place Trickle Charger in Trunk

Work Procedure

1. Place trickle charger in truck.

Primary Parts Information

Qty.	Part Name	Part Number
1	Trickle charger	A0009822921

Note: The following allowable labor operation should be used when submitting a warranty claim for this repair:

Warranty Information

Damage Code	Operation Number	Description	
54 902 05	12-1875	Place trickle charger in vehicle	0.1

Note: Always check Xentry Operation Time (XOT) for the current OP-Code times. Labor times are subject to change and updates may not be reflected in this document.